3/10/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG20013306/KGS3Q2

Date:

10/03/2021

REFERENCE

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2070149850

Claimant Vehicle

SHC5483X

Insured Vehicle No:

SKS4848P

No: Date of Loss:

27/11/2020

Nature of Claim:

TP

Claim No:

3864588267SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHC5483X

N/A

Make & Model:

RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)

Engine No: Chassis No: **HIDDEN**

Reg. Date:

11/07/2014 (Man. Year: 2014)

Odometer:

VF1ABL15AUC277525 72390 km

Colour:

Metallic White/Red

Engine Capacity: Market Value/New Car Price: 1995 cc

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification: Yes

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side: Front Right Side: 215/60 R16 Sailun 9 mm Sailun 9 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 215/60 R16 Sailun 7 mm

Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,199.98	571.53	4,628.45	89.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,750.00	420.00	4,330.00	91.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,949.98	991.53	8,958.45	90.03
Approved Total (Overridden) (S\$)		800.00		
(S\$)	9,949.98	800.00	9,149.98	91.96
+ GST 7.00/7.00% (S\$)	696.50	56.00	640.50	91.96
Nett Amount (S\$)	10,646.48	856.00	9,790.48	91.96
Global Sur	Global Sum Settlement (S\$)			

INSPECTION

Date Inspected:

Date of Assignment:

01/12/2020

01/12/2020 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)

2, Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair:

1.5 days

KENNETH KONG Adjuster:

Manager:

Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

					Repairer's	Amount
	1		*BUMPER COVER REAR	Buckled / Dented	561.70 FL	*561.70 FL
	1		*BUMPER LOWER REAR	Serviceable	411.90 FL	*- FL
	1		*BUMPER BEAM REAR	Repair	547.80 FL	*- FL
	1		*BUMPER BEAM BRACKET LH REAR	Serviceable	114.50 FL	*- FL
	1		*BUMPER BEAM BRACKET RH REAR	Serviceable	114.50 FL	*- FL
	1		*FENDER PANEL REAR RH	Repair	1,933.20 FL	*- FL
	1		*FENDER BRACKET LOWER RH	Serviceable	11.80 FL	*- FL
	1		*TAILLAMP RH	Serviceable	401.40 FL	*- FL
	1		*WHEELARCH REAR RH	Serviceable	275.40 FL	*- FL
0	1		*SET FENDER SCREW	Not Necessary	60.00 FS	*- FS
1	1		*SET CLIP ,FRONT FENDER LINER	Not Necessary	65.00 FS	*- FS
2	1		*BUMPER CLIP FRT	Necessary	90.00 FS	*66.00 FS
3	1		*BUMPER RETAINER CLIP FRT	Not Necessary	75.00 FS	*- FS
4	1		*WHEELARCH CLIP FRT	Not Necessary	75.00 FS	*- F\$
5	1		*DOOR FINISHER CLIP KIT FRT RH	Not Necessary	90.00 FS	*- FS
6	1		*DOOR MOULDING CLIP L70Y	Not Necessary	80.00 FS	*- F\$
7	1		*DOOR MOULDING SCREW L70Y	Not Necessary	65.00 FS	*- F\$
8	1		*DOOR CASING CLIP	Not Necessary	85.00 FS	*- F\$
9	1		*REAR DOOR STICKER 6555-3333	Not Necessary	100.00 FS	*- FS
0	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
1	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
2	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS
=Frai	nchise _l	part. S=SpcNe	ett. L=ListItemDisc.	-		
				Sub Total (S\$)	5,637.20	627.70
			- List Item Discount on L Items 10.00/10.00% (S\$)			56.17
				Total Parts (S\$)	5,199.98	571.53

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TOWING FEES	New	170.00	0.00
2	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	300.00	0.00
3	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
4	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
6	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,400.00	200.00
7	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	220.00
9	TO TRANSFER OF TIRE RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
	Gross Labour Cost (S\$)		4,750.00	420.00
	Report was unsubmitted during this pr	int-out.		

< END OF ESTIMATES >