



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 3112K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	IONIQV2&3 COVER-FR BUMPER	CRACKED	430.90	430.90
1	IONIQV1-3 LAMP ASSY-HEAD	SCRATCHED	1,993.65	1,993.65
	LESS 20% DISCOUNT		-484.91	-484.91
			1,939.64	1,939.64
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	320.00
	SPRAYPAINT CHARGE.		300.00	200.00
	CHECK ALL LIGHTING.		50.00	20.00
			750.00	540.00
	GRAND TOTAL		2,689.64	2,479.64
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,479.64

Report Ref No. NS/INC20013307/Ntf3e2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.