

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20013309/GVD3E2
Date: 29/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100466245
Claimant Vehicle No : SDE9339R **Insured Vehicle No :** SJN234A
Date of Loss: 27/11/2020 Nature of Claim: TP Claim No: 3577445631SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDE9339R**
Make & Model: TOYOTA HARRIER, 2.0 (A) Engine No: 3ZRB874334
Reg. Date: 24/10/2016 (Man. Year: 2016) Chassis No: ZSU600088264
Colour: Silver Odometer: 65755 km
Engine Capacity: 1986 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18
Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/12/2020
Date Inspected: 07/12/2020 Inspected At: KOI MOTOR WORKS (HQ)
BLK 176 SIN MING DRIVE #04-12 SIN MING
AUTOCARE
Singapore 575721
Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER BRACKET	Bent	0.00 F	*- F
4	1		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
5	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
6	1		*FRT BUMPER SENSOR	Damaged	0.00 F	*- F
7	1		*FRT RH BUMPER FOG LAMP COVER	Deformed	0.00 F	*- F
8	1		*FRT RH BUMPER FOG LAMP	Broken	0.00 F	*- F
9	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
10	1		*FRT RH FENDER	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$) **0.00** **0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >