

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013313/ETD3E2

Date: 10/02/2021

REFERENCE

Insured/Claimant:	SURIAH BINTE SELAMAT	Policy No:	1900259600	
Date of Loss:	02/12/2020	Nature of Claim:	OD	Claim No: 5850615644SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR583K	Engine No:	G4FGKH751124
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF5416ML5057708
Reg. Date:	17/12/2019 (Man. Year: 2019)	Odometer:	13158 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$84,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,098.00	2,962.40	2,135.60	41.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	2,030.00	600.00	22.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,728.00	4,992.40	2,735.60	35.40
+ GST 7.00/7.00% (S\$)	540.96	349.47	191.49	35.40
Nett Amount (S\$)	8,268.96	5,341.87	2,927.09	35.40

INSPECTION

Date of Assignment:	03/12/2020	
Date Inspected:	03/12/2020 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*LAMP ASSY-HEAD, RH	Broken	2,210.00 FL	*2,210.00 FL
3	1		*PANEL-FENDER, RH	Dented	430.00 FL	*430.00 FL
4	1		*COVER-FR BUMPER	Cut / Deformed	633.00 FL	*633.00 FL
5	1		*GRILLE ASSY-RADIATOR	Not Necessary	328.00 FL	*- FL
6	4		*GRILLE-FRONT BUMPER	Not Necessary	1,940.00 FL	*- FL
7	1		*MOULDING-FRONT BUMPER, RH	Cut	216.00 FL	*216.00 FL
8	1		*LAMP ASSY-SIDE REPEATER, RH	Cut	143.00 FL	*143.00 FL
9	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	84.00 FL	*- FL
10	1		*AIR DUCT-FR BUMPER, RH	Broken	14.00 FL	*14.00 FL
11	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
12	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	163.00 FL	*- FL
13	1		*GUARD ASSY-FRONT WHEEL, RH	Not Necessary	95.00 FL	*- FL
14	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,360.00	3,698.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,262.00	735.60
Total Parts (S\$)	5,098.00	2,962.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER, FRT RH FENDER & AFFECTED AREA	New	1,200.00	800.00
2	PAINT WORK ON FRT BUMPER & FRT RH FENDER	New	960.00	960.00
3	REMOVE & INSTALL FRONT PARKING ASSIST	New	120.00	120.00
4	PERFORM RUST PREVENTION	New	40.00	0.00
5	CHECK CHASSIS & WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	TO APPLY ZERTONA COATING ON AFFECTED AREA	New	160.00	0.00
Gross Labour Cost (\$\$)			2,630.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >