

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20013314/R1VF3Q2

Date: 19/01/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SME6618Z

Insured Vehicle No : GBK1876B

Date of Loss: 28/11/2020

Nature of Claim:

TP

Claim No: CDMCG20001789

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME6618Z**

Make & Model: HONDA CIVIC, 1.6 VTI CVT (A)

Engine No: R16B25501623

Reg. Date: 10/10/2018 (Man. Year: 2018)

Chassis No: MRHFC5650JT001386

Colour: Red

Odometer: 15942 km

Engine Capacity: 1597 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55R16

Rear Tyre Size:

215/55R16

Front Left Side: Hankook 6 mm

Rear Left Side:

Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side:

Hankook 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 2,230.86 | 615.07 | 1,615.79 | 72.43 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,960.00 | 2,520.00 | 2,440.00 | 49.19 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (\$\$) | 7,190.86 | 3,135.07 | 4,055.79 | 56.40 |
| + GST 7.00/7.00% (\$\$) | 503.36 | 219.45 | 283.91 | 56.40 |
| Nett Amount (\$\$) | 7,694.22 | 3,354.52 | 4,339.70 | 56.40 |

INSPECTION

Date of Assignment: 03/12/2020

Date Inspected: 07/12/2020 Inspected At:

Kah Motor Co Sdn Bhd
(ALEXANDRA)
255 ALEXANDRA ROAD
Singapore -

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 12 Jan 2021) |
| Parts: | 143 | HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SME6618Z) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-----|-----|---|---------------|------------|------------|
| 1 | 1 | *FACE,FR BUMPER | Deformed | 434.92 FS | *434.92 FS |
| 2 | 1 | *GRILLEFR BUMPER LOWER | Serviceable | 29.62 FS | *- FS |
| 3 | 1 | *GARNISHR.FR BUMPER SIDE | Scratched | 14.77 FS | *11.70 FS |
| 4 | 1 | *BEAM COMPFR BUMPER | Not Necessary | 283.42 FS | *- FS |
| 5 | 1 | *BEAMR.FR BUMPER UPPER | Not Necessary | 21.82 FS | *- FS |
| 6 | 1 | *BEAM COMPFR BUMPER CENTER UPP | Not Necessary | 176.02 FS | *- FS |
| 7 | 1 | *SPACERR FR BUMPER SIDE | Necessary | 7.80 FS | *7.80 FS |
| 8 | 1 | *SPACERL FR BUMPER SIDE | Not Necessary | 7.80 FS | *- FS |
| 9 | 1 | *CLIP BUMPER (16 Pcs) | Necessary | 27.60 FS | *27.60 FS |
| 10 | 1 | *BASE FR GRILLE CHROME | Cracked | 60.45 FS | *60.45 FS |
| 11 | 1 | *MOLDINGFR GRILLE | Not Necessary | 82.27 FS | *- FS |
| 12 | 1 | *EXTENSION ASSYR FR GRILLE | Not Necessary | 70.20 FS | *- FS |
| 13 | 1 | *EMBLEM | Necessary | 12.30 FS | *12.30 FS |
| 14 | 1 | *NUTPUSH 3MM (2 Pcs) | Necessary | 3.15 FS | *3.15 FS |
| 15 | 1 | *PANELR FENDER | Repair | 338.10 FS | *- FS |
| 16 | 1 | *FENDERR FR INNER | Not Necessary | 41.85 FS | *- FS |
| 17 | 1 | *HEADLIGHT ASSY R | Serviceable | 479.92 FS | *- FS |
| 18 | 1 | *SUNDRIES | Necessary | 100.00 FS | *30.00 FS |
| 19 | 1 | *LIGHT ASSYR SIDE TURNLIGHT ASSYR SIDE TURN | Cracked | 27.15 FS | *27.15 FS |
| 20 | 1 | *GARNISHR FR BUMPER SIDE | Repeated | 11.70 FS | *- FS |

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **2,230.86** **615.07**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | INSPECT FR LIGHTING MECHANISMS & FOCUS | New | 280.00 | 180.00 |
| 2 | REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON | New | 2,600.00 | 1,300.00 |
| 3 | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (3P) | New | 2,080.00 | 1,040.00 |
| Gross Labour Cost (\$\$) | | | 4,960.00 | 2,520.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >