

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20013322/QPA3Q2
Date: 18/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100443750-04
Claimant Vehicle No :	SME7285T	Insured Vehicle No :	SKZ8020Y
Date of Loss:	29/11/2020	Nature of Claim:	TP
		Claim No:	2527864863SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME7285T		
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No:	2ZR0C08769
Reg. Date:	15/10/2018 (Man. Year: 2018)	Chassis No:	ZWR800335247
Colour:	Silver	Odometer:	167787 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Arivo 6 mm	Rear Left Side:	Arivo 6 mm
Front Right Side:	Arivo 6 mm	Rear Right Side:	Arivo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,567.61	2,314.69	3,252.92	58.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,360.00	1,780.00	580.00	24.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,927.61	4,094.69	3,832.92	48.35
Approved Total (Overridden) (S\$)		3,250.00		

(S\$)	7,927.61	3,250.00	4,677.61	59.00
+ GST 7.00/7.00% (S\$)	554.93	227.50	327.43	59.00
Nett Amount (S\$)	8,482.54	3,477.50	5,005.04	59.00
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,664.95		
Global Sum Settlement (S\$)		3,650.00		

INSPECTION

Date of Assignment: 03/12/2020

Date Inspected: 03/12/2020

Inspected At: My Car Consultant Pte Ltd (HQ)
60 Jalan Lam Huat,, Carros Centre #05-67/68
Singapore 737869

Estimated Period of Repair: 4.0 days

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crumpled	751.20 FL	*751.20 FL
2	1		*REAR BUMPER REFLECTOR RH	Cracked	159.00 FL	*159.00 FL
3	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	171.45 FL	*- FL
4	2		*REAR BUMPER SIDE RH	Repair	312.20 FL	*- FL
5	1		*TAILGATE	Dented	2,110.25 FL	*1,700.00 FL
6	1		*TAILGATE EMBLEM	Necessary	45.00 FL	*45.00 FL
7	1		*TAILGATE WEATHERSTRIPE	Cut	391.05 FL	*391.05 FL
8	1		*FENDER INNER TRIM RH	Serviceable	1,417.70 FL	*- FL
9	1		*REAR END PANEL	Repair	1,100.85 FL	*- FL
10	1		*REAR END PANEL TOP GAR	Serviceable	391.45 FL	*- FL
11	1		*REAR BUMPER REVERSE SENSOR	Serviceable	220.00 FS	*- FS
12	10		*REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
13	1		*REAR END PANEL SEALANT	Serviceable	120.00 FS	*- FS
14	1		*SET REAR FENDER INNER TRIM CLIP	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,280.15	3,076.25
- List Item Discount on L Items 25.00/25.00% (\$)	1,712.54	761.56
Total Parts (\$)	5,567.61	2,314.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING	New	80.00	30.00
2	ANTI RUST COAT	New	150.00	40.00
3	R+R RR WINDSCREEN	New	180.00	120.00
4	R+R RR SEATS	New	120.00	0.00
5	PANEL BEATING ON AFFECTED AREA RR SPARE TYRE PANEL	New	800.00	800.00
6	SPRAY ON AFFECTED AREA & RR FENDER X2	New	800.00	700.00
7	R+R TAILGATE MECHANISM	New	150.00	60.00
8	R+R REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (S\$)			2,360.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >