

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG20013323/AQD3Q2

Date: 08/03/2021

REFERENCE

Insured/Claimant: REYJAL FABIEN ALEXANDRE

Policy No: 2100470715

Date of Loss: 27/11/2020

Nature of Claim: OD

Claim No: 5168879210SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD3865M**

Make & Model: AUDI A3, 1.4 SEDAN TFSI (ATTRACTION) (A)

Engine No: CZC521901

Reg. Date: 15/06/2016 (Man. Year: 2016)

Chassis No: WAUZZZ8V4GA106079

Colour: Silver

Odometer: 0 km

Engine Capacity: 1395 cc

Market Value/New Car Price: S\$70,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size: 205/55R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,255.00	1,909.36	4,345.64	69.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,922.00	1,242.00	3,680.00	74.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,177.00	3,151.36	8,025.64	71.80
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	10,577.00	2,551.36	8,025.64	75.88
+ GST 7.00/7.00% (S\$)	740.39	178.60	561.79	75.88
Nett Amount (S\$)	11,317.39	2,729.96	8,587.43	75.88

INSPECTION

Date of Assignment: 03/12/2020

Date Inspected: 03/12/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,842.00 FS	*1,473.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	185.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Deformed	154.00 FS	*123.20 FS
4	4		*FRONT BUMPER PULL STRAP-LOWER	Damaged	204.00 FS	*162.88 FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	108.00 FS	*- FS
6	1		*RADIATOR GRILLE	Not Necessary	683.00 FS	*- FS
7	1		*RADIATOR GRILLE COVER	Not Necessary	97.00 FS	*- FS
8	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
9	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
10	1		*FRONT REINFORCEMENT BEAM	Not Necessary	715.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	82.00 FS	*- FS
12	1		*FOAM FILLER PIECE COVER	Not Necessary	55.00 FS	*- FS
13	1		*RADIATOR AIR GUIDE-LH	Not Necessary	24.00 FS	*- FS
14	1		*FRONT BUMPER HOISE INSULATION	Not Necessary	264.00 FS	*- FS
15	1		*WHEEL HOUSING LINER-LH	Torn	167.00 FS	*133.20 FS
16	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	88.00 FS	*- FS
17	1		*LIFT CYLINDER-LH	Not Necessary	190.00 FS	*- FS
18	1		*FRONT FENDER-LH	Not Necessary	841.00 FS	*- FS
19	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	71.00 FS	*- FS
20	1		*FRONT FENDER CLOSING ELEMENT	Not Necessary	61.00 FS	*- FS
21	1		*FRONT FENDER BRACKET-LH	Not Necessary	47.00 FS	*- FS
22	1		*FRONT FENDER BRACE	Not Necessary	95.00 FS	*- FS
23	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
24	1		*SUNDRIES	Necessary	200.00 FS	*16.48 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **6,255.00** **1,909.36**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			4,922.00	1,242.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >