

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013325/DGA3Q2
Date: 15/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800041912
Claimant Vehicle No :	SKZ7142K	Insured Vehicle No :	SKF8191S
Date of Loss:	02/12/2020	Nature of Claim:	TP
		Claim No:	3165728894SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ7142K		
Make & Model:	MAZDA CX-5, 2.0 (A)	Engine No:	PE10290847
Reg. Date:	29/01/2016 (Man. Year: 2015)	Chassis No:	JM6KE1072G0349854
Colour:	Silver	Odometer:	82926 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,515.48	5,889.08	16,626.40	73.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,850.00	2,010.00	2,840.00	58.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,365.48	7,899.08	19,466.40	71.13
Approved Total (Overridden) (S\$)		6,300.00		

(S\$)	27,365.48	6,300.00	21,065.48	76.98
+ GST 7.00/7.00% (S\$)	1,915.58	441.00	1,474.58	76.98
Nett Amount (S\$)	29,281.06	6,741.00	22,540.06	76.98
+ Car Rental (8.0 x S\$120.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		7,737.45		

INSPECTION

Date of Assignment: 03/12/2020

Date Inspected: 04/12/2020

Estimated Period of Repair: 5.0 days

Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
 Singapore 568047

Adjuster: BRYAN TANI**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,870.00 FL	*1,448.00 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	324.00 FL	*183.10 FL
3	1		*TAILGATE LOGO	Necessary	84.60 FL	*84.60 FL
4	1		*TAILGATE SKY-ACTIV EMBLEM	Necessary	95.00 FL	*95.00 FL
5	1		*TAILGATE CX5 EMBLEM	Necessary	88.00 FL	*88.00 FL
6	1		*TAILGATE CENTER GARNISH	Not Necessary	382.00 FL	*- FL
7	2		*TAILGATE NO PLATE LAMP LH/RH	Not Necessary	104.00 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP	Necessary / Deformed	283.00 FL	*283.00 FL
9	1		*TAILGATE INNER TRIM BOARD	Not Necessary	380.00 FL	*- FL
10	1		*TAILGATE LOCK	Damaged	383.00 FL	*250.80 FL
11	1		*TAILGATE SWITCH	Not Necessary	156.00 FL	*- FL
12	2		*TAILGATE LAMP LH/RH	Not Necessary	980.00 FL	*- FL
13	1		*TAILGATE INNER HANDLE	Not Necessary	136.00 FL	*- FL
14	1		*TAILGATE STOPPERS	Not Necessary	10.60 FL	*- FL
15	2		*TAILGATE HINGE LH/RH	Not Necessary	116.00 FL	*- FL
16	2		*TAILGATE DAMPER LH/RH	Not Necessary	462.00 FL	*- FL
17	2		*TAIL LAMP LH/RH	Not Necessary	2,522.00 FL	*- FL
18	2		*TAIL LAMP LOWER BRACKET LH/RH	Not Necessary	210.00 FL	*- FL
19	1		*REAR BUMPER	Dented	1,687.00 FL	*1,218.00 FL
20	2		*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	92.00 FL	*- FL
21	1		*REAR BUMPER LOWER LID (NPA)	No such part	0.00 FL	*- FL
22	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	212.00 FL	*- FL
23	4		*REAR BUMPER SENSOR	Damaged (2 PCS ONLY)	924.00 FL	*462.00 FL
24	4		*REAR BUMPER SENSOR HOLDER	Serviceable	140.00 FL	*- FL
25	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	1,134.00 FL	*- FL
26	1		*REAR REINFORCEMENT BAR	Dented	814.00 FL	*543.00 FL
27	1		*REAR END PANEL	Dented	876.00 FL	*476.10 FL
28	1		*REAR END PANEL TOP GARNISH	Mtg Cracked	279.00 FL	*279.00 FL
29	1		*REAR KEYLESS SENSOR	Mtg Cracked	256.00 FL	*256.00 FL
30	1		*REAR KEYLESS BUZZER	Not Necessary	212.00 FL	*- FL
31	1		*SPARE WHEEL PANEL	Not Necessary	1,090.00 FL	*- FL
32	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	229.00 FL	*- FL
33	2		*SPARE WHEEL QUARTER PANEL LH/RH (NPA)	Not Necessary	0.00 FL	*- FL
34	2		*SPARE WHEEL TOOL BOX LH/RH (NPA)	Not Necessary	0.00 FL	*- FL
35	2		*REAR FENDER LH/RH	Not Necessary	4,092.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*REAR FENDER INNER TRIM BOARD LH/RH	Not Necessary	868.00 FL	*- FL
37	2		*REAR FENDER QUARTER GLASS MOULDING LH/RH	Not Necessary	372.00 FL	*- FL
38	1		*REAR EXHAUST PIPE	Dented	1,954.00 FL	*1,551.00 FL
39	1		*REAR EXHAUST MOUNTING	Not Necessary	128.00 FL	*- FL
40	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	172.00 FL	*- FL
41	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
42	1		*TAILGATE WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
43	1		*TAILGATE CENTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
46	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
47	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS
48	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
49	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
50	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
51	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
52	1		*REAR FENDER QUARTER GLASS DAMPING SEAL	Not Necessary	30.00 FS	*- FS
53	1		*REAR NO.PLATE & CASING	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	24,927.20	7,332.60
- List Item Discount on L Items 10.00/20.00% (\$)	2,411.72	1,443.52
Total Parts (\$)	22,515.48	5,889.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL ITERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,400.00	700.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,400.00	800.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	80.00
6	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	40.00
7	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	New	300.00	120.00
8	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	200.00	0.00
9	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
10	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
11	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
Gross Labour Cost (S\$)			4,850.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >