

JWG INTERNATIONAL PTE. LTD.

100 MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

TEL: 6299 6103 | FAX: 6909 9592

EMAIL: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SKF8191S [YOUR INSURED] & SKZ7142K [OUR CLIENT]
ON 02/12/2020.

ESTIMATED REPAIR COSTS FOR SKZ7142K

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	TAILGATE <i>Dent</i>	1448.00	\$1,830.00 ✓
1PC	TAILGATE WINDSCREEN MOULDING <i>Nec</i>	183.10	\$324.00 ✓
1PC	TAILGATE LOGO <i>Nec</i>		\$84.60 ✓
1PC	TAILGATE 'SKY-ACTIV' EMBLEM <i>Nec</i>		\$95.00 ✓
1PC	TAILGATE 'CX5' EMBLEM <i>Nec</i>		\$88.00 ✓
1PC	TAILGATE CENTER GARNISH <i>HH</i>		\$382.00 X
2PCS	TAILGATE NO. PLATE LAMP LH / RH @ \$ <i>HH</i> \$52.00 EACH		\$104.00 X
1PC	TAILGATE WEATHER STRIP <i>Nec [advised]</i>		\$283.00 ✓
1PC	TAILGATE INNER TRIM BOARD <i>HH</i>		\$380.00 X
1PC	TAILGATE LOCK <i>Dent</i>	250.80	\$383.00 ✓
1PC	TAILGATE SWITCH <i>HH</i>		\$156.00 X
2PCS	TAILGATE LAMP LH / RH @ \$ <i>HH</i> \$490.00 EACH		\$980.00 X
1PC	TAILGATE INNER HANDLE <i>HH</i>		\$136.00 X
1PC	TAILGATE STOPPERS <i>HH</i>		\$10.60 X
2PCS	TAILGATE HINGE LH / RH @ \$ <i>HH</i> \$58.00 EACH		\$116.00 X
2PCS	TAILGATE DAMPER LH / RH @ \$ <i>HH</i> \$231.00 EACH		\$462.00 X
2PCS	TAIL LAMP LH / RH @ \$ <i>HH</i> \$1,261.00 EACH		\$2,522.00 X
2PCS	TAIL LAMP LOWER BRACKET LH / RH @ \$ <i>HH</i> \$105.00 EACH		\$210.00 X
1PC	REAR BUMPER <i>Dent</i>	1218.00	\$1,657.00 ✓
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$ <i>svc</i> \$46.00 EACH		\$92.00 X
1PC	REAR BUMPER LOWER LID <i>NS</i>		— X
2PCS	REAR BUMPER REFLECTOR LH / RH @ \$ <i>HH</i> \$106.00 EACH		\$212.00 X
4PCS	REAR BUMPER SENSOR @ \$ <i>2 pc</i> <i>Dent</i> \$231.00 EACH \$46.00		\$924.00 ✓
4PCS	REAR BUMPER SENSOR HOLDER @ \$ <i>svc</i> \$35.00 EACH		\$140.00 X
1PC	REAR BUMPER SENSOR WIRE HARNESS <i>HH</i>		\$1,134.00 X
1PC	REAR REINFORCEMENT BAR <i>Dent</i>	543.00	\$814.00 ✓
1PC	REAR END PANEL <i>Dent</i>	476.10	\$876.00 ✓
1PC	REAR END PANEL TOP GARNISH <i>minorly crack</i>		\$279.00 ✓
1PC	REAR KEYLESS SENSOR <i>minorly crack</i>		\$256.00 ✓
1PC	REAR KEYLESS BUZZER <i>HH</i>		\$212.00 X

	SPARE WHEEL PANEL HH	\$1,090.00	X
	SPARE WHEEL PANEL TOP BOARD HH	\$229.00	X
	SPARE WHEEL QUARTER PANEL LH / RH @ \$ HH	-	X
	SPARE WHEEL TOOL BOX LH / RH @ \$ HH	-	X
1S	REAR FENDER LH / RH @ \$ HH \$2,046.00 EACH	\$4,092.00	X
1CS	REAR FENDER INNER TRIM BOARD LH / RH @ \$ HH \$434.00 EACH	\$868.00	X
1PC	REAR FENDER QUARTER GLASS MOULDING LH / RH @ \$ HH \$186.00	\$372.00	X
1PC	REAR EXHAUST PIPE Denda 1551.00	\$1,954.00	✓
1PC	REAR EXHAUST MOUNTING HH	\$128.00	X
1PC	REAR EXHAUST HEAT SHIELD HH	\$172.00	X

7217.60
202. 5774.08

PARTS SUM: \$
PARTS LESS 10%: \$ 202.-
PARTS TOTAL: \$ -

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY TAILGATE WINDSCREEN SEALANT HLC	\$ 80.00	40/-
*	TO SUPPLY TAILGATE WINDSCREEN DAMPING SEAL HH	\$ 30.00	X
*	TO SUPPLY TAILGATE CENTER GARNISH CLIPS HH	\$ 50.00	X
*	TO SUPPLY TAILGATE INNER TRIM BOARD CLIPS HH	\$ 50.00	X
*	TO SUPPLY REAR BUMPER CLIPS HLC	\$ 50.00	20/-
*	TO SUPPLY REAR END PANEL SEALANT HLC	\$ 80.00	40/-
*	TO SUPPLY REAR END PANEL TOP GARNISH CLIPS HLC	\$ 50.00	15/-
*	TO SUPPLY SPARE WHEEL PANEL SEALANT HH	\$ 80.00	X
*	TO SUPPLY REAR FENDER SEALANT HH	\$ 80.00	X
*	TO SUPPLY REAR FENDER INNER TRIM CLIPS HH	\$ 50.00	X
*	TO SUPPLY REAR FENDER QUARTER GLASS SEALANT HH	\$ 80.00	X
*	TO SUPPLY REAR FENDER QUARTER GLASS DAMPING SEAL HH	\$ 30.00	X
*	TO SUPPLY REAR NO. PLATE & CASING HH	\$ 100.00	X
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00	80/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 1,400.00	700/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 1,400.00	800/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00	40/-
*	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	\$ 200.00	80/-
*	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	\$ 150.00	40/-
*	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	\$ 300.00	120/-
*	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	\$ 200.00	HH

TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	\$ 100.00	74
TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	2010.00	\$ 200.00 44
TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00	150/-

LABOUR & S/N TOTAL: \$ 5,660.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 5,660.00

04/12/2020 @ 1100hrs

N/A Antenna

2/snm 5 days.

Yan

LKK Auto

[Signature]

7899.08

1/s 6300/-

US \$ 7,751.58

≈ \$ 7,750.00

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: