

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20013330/AGS3Q2
Date: 10/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100049458-13
Claimant Vehicle No :	SKS2183L	Insured Vehicle No :	SGZ8654R
Date of Loss:	30/11/2020	Nature of Claim:	TP
		Claim No:	5046805418SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS2183L		
Make & Model:	MAZDA 3, 1.5 4 DOOR SEDAN SP (A)	Engine No:	P520262528
Reg. Date:	30/03/2015 (Man. Year: 2015)	Chassis No:	JM6BM42A8G0301356
Colour:	Black	Odometer:	102022 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,691.80	1,517.36	2,174.44	58.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	680.00	1,170.00	63.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,541.80	2,197.36	3,344.44	60.35
Approved Total (Overridden) (S\$)		1,700.00		

Nett Amount (S\$)	5,541.80	1,700.00	3,841.80	69.32
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,857.49		

INSPECTION

Date of Assignment: 02/12/2020

Date Inspected: 02/12/2020

Inspected At:

Leang Automotive (HQ)
 BLK 1 KAKI BUKIT AVE 6 #02-12 AUTOBAY@ KAKI BUKIT
 Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,062.50 F	*1,062.50 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	2		*REAR BUMPER SIDE HOLDER	Not Necessary	70.00 F	*- FL
4	1		*REAR BUMPER REFLECTOR RH	Cracked	54.90 F	*54.90 FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	491.80 F	*491.80 FL
6	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
7	1		*REAR END PANEL	Not Necessary	559.60 F	*- FL
8	1		*REAR END PANEL TOP GARNISH	Not Necessary	168.00 F	*- FL
9	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
10	1		*TAILLAMP RH	Not Necessary	915.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,691.80	1,839.20
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	321.84
Total Parts (\$)	3,691.80	1,517.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	300.00
2	SPRAY PAINTING	New	600.00	300.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO SPRAY TUFF COAT	New	150.00	0.00
6	TO REMOVE UPHOLSTERY	New	150.00	0.00
Gross Labour Cost (S\$)			1,850.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >