

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20013335/QPA3Q2

Date: 09/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100476992

Claimant
Vehicle No : SHD6269L **Insured Vehicle No :** SLE5840R

Date of Loss: 25/11/2020 Nature of Claim: TP Claim No: 9793148780SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6269L	Engine No:	2ZR2F33082
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU303089219
Reg. Date:	26/12/2019 (Man. Year: 2019)	Odometer:	118007 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,332.70	425.63	2,907.07	87.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,845.00	460.00	1,385.00	75.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	5,177.70	885.63	4,292.07	82.90
+ Loss of Use (2.0 x S\$50.00/day) (\$\$)		100.00		
+ Car Rental (2.0 x S\$120.38/day) (\$\$)		240.76		
+ Doc/Search Fee (\$\$)		7.00		
Nett Liability (\$\$)		1,233.39		
Global Sum Settlement (\$\$)		1,230.00		

INSPECTION

Date of Assignment: 26/11/2020

Date Inspected: 26/11/2020 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GUARD ,RR BUMPER ,LOWER (DISC 25%)	Crumpled	374.50 F	*280.88 F
2	3		*PAD ,RR BUMPER ,CTR (DISC 25%)	Necessary	33.00 F	*24.75 F
3	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
4	2		*PAD ,RR BUMPER ,RH & LH ,1	Serviceable	4.00 F	*- F
5	2		*PAD ,RR BUMPER ,RH & LH ,2	Serviceable	4.00 F	*- F
6	2		*PAD ,RR BUMPER ,RH & LH ,3	Serviceable	11.00 F	*- F
7	2		*SEAL ,RR BUMPER ARM ,RH & LH	Serviceable	11.30 F	*- F
8	1		*RETAINER ,RR BUMPER ,RH	Serviceable	132.60 F	*- F
9	1		*RETAINER ,RR BUMPER ,LH	Serviceable	132.60 F	*- F
10	1		*CLIP PIECE ,FRT & RR BUMPER	Serviceable	4.50 F	*- F
11	1		*COVER ,GUARD RR BUMPER LOWER	Serviceable	22.00 F	*- F
12	1		*REAR BUMPER EFLECTOR ASSY ,REFLEX ,RH	Serviceable	39.00 F	*- F
13	1		*REAR BUMPER EFLECTOR ASSY ,REFLEX ,LH	Serviceable	39.00 F	*- F
14	1		*REAR BUMPER REINFORCEMENT	Serviceable	332.70 F	*- F
15	1		*ANTENNA ,ELECTRICAL KEY	Serviceable	72.00 F	*- F
16	1		*REVERSE SENSOR ,REAR BUMPER	Serviceable	180.00 F	*- F
17	1		*COVER ,REAR FLOOR UNDER ,RH	Serviceable	175.10 F	*- F
18	1		*COVER ,REAR FLOOR UNDER CENTER	Serviceable	229.90 F	*- F
19	1		*COVER ,REAR FLOOR UNDER ,LH	Serviceable	241.90 F	*- F
20	1		*END PANEL SUB-ASSY ,BODY LOWER BACK	Serviceable	651.00 F	*- F
21	1		*SEALANT SIKAFLEX	Serviceable	37.00 F	*- F
22	1		*COVER ,RR BUMPER ASSY	Repair	485.60 F	*- F

F=Franchise part.

Total Parts (\$\$) **3,332.70** **425.63**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	507.00	200.00
2	SPRAY PAINT	New	738.00	200.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
5	TO REMOVE AND REFIT REAR HARDESS	New	120.00	20.00
6	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	0.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
8	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			1,845.00	460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >