Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20013338/QQD3Q2

502109 km

Date: 01/03/2021

Odometer:

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Polic

Policy No:

Claimant SMB1605J Vehicle No:

Insured Vehicle No: YQ1634D

iligated vehicle No. 100-D

Date of Loss: 30/11/2020 Nature of Claim: TP Claim No: CDMCG20001790

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMB1605J

 Make & Model:
 MAN NL320F (A22), 10.5 D ABS TURBO (A)
 Engine No:
 50339501213946

 Reg. Date:
 28/01/2015 (Man. Year: 2014)
 Chassis No:
 WMAA22ZZ3F7002582

Colour: Multi-colour

Engine Capacity: 10518 cc

Market Value/New Car

Price:

N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70R22.5 Rear Tyre Size: 275/70R22.5 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,841.70	6,214.03	627.67	9.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,468.00	2,033.00	435.00	17.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,309.70	8,247.03	1,062.67	11.41
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	9.309.70	7.000.00	2.309.70	24.81

INSPECTION

Date of Assignment: 03/12/2020

Date Inspected: 04/12/2020 Inspected At: SMRT Automotive Services Pte Ltd

(Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Reference				
Part Source	:	(Last Synchronised: 25 Feb 2021)		
Parts:	N/A	MAN NL320F (A22) 10.5 D ABS TURBO (A) (Model not available in database)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for SMB1605J)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WINDSCREEN,FRONT;R OR MAN A22 BUS	Broken	5,031.80 F	*5,031.80 FL
2	1		*MIRROR VIEW;FRONT,RH,FOR MAN	Crumpled	1,244.90 F	*1,244.90 FL
3	1		*IU BRACKET	Necessary	35.00 FS	*35.00 FS
4	1		*PRIMER (SIKA 206 G+P)	Necessary	80.00 FS	*80.00 FS
5	10		*ADHESIVE;DIRECT GLAZING	Necessary	370.00 FS	*370.00 FS
6	1		*ACTIVATOR	Necessary	80.00 FS	*80.00 FS
F=Fra	nchise	part. S=SpcN	Nett. L=ListItemDisc.			
			S	ub Total (S\$)	6,841.70	6,841.70
	- List Item Discount on L Items 0.00/10.00% (S\$)			0.00	627.67	
			То	tal Parts (S\$)	6,841.70	6,214.03
Report was unsubmitted during this print-out.						

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,590.00	1,325.00
2	TO PUTTY & RESPRAY	New	878.00	708.00
	Gross Labou	r Cost (S\$)	2,468.00	2,033.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >