

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP20010014

Date: 24 JUN 2020

Goh Ching Siang Trading
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 489978

THIRD PARTY SURVEY ACCIDENT OCCURED ON 21 JAN 2020

Workshop Name and Address

Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 489978

As per your instruction dated 04 FEB 2020
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
GBB9329J

1. VEHICLE PARTICULARS

Registration No : GBB9329J
Model : TOYOTA DYNA 150
Year / Capacity : Mar 2009 / 2982 cc
Chassis No : JTFAT35Y30K200393

Engine No : 1KD1913568
Mileage : 732 619km
Colour : Metallic blue

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	195/50/R15	Bridgestone	9.00 mm	Normal
REAR O/S :	155 R 12	Bridgestone	9.00 mm	Normal
FRONT N/S :	195/50/R15	Bridgestone	9.00 mm	Normal
REAR N/S :	155 R 12	Bridgestone	9.00 mm	Normal

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the Rear & side portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 05 working days to complete

5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : GBB9329J

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>List Items</i>				
1 pc	Tailboard with hinges	Bent/deformed	\$ 1,464.80	\$ 1,464.80
2 pcs	Tailboard lock	Damaged	\$ 237.60	\$ 237.60
4 pcs	Tailboard rubber stopper	Warped/deformed	\$ 148.60	\$ 148.60
1 pc	Tailboard lower member	Bent/distorted	\$ 289.90	\$ 289.90
2 pcs	Side gate support hinges	distorted	\$ 110.00	\$ 110.00
2 pcs	Side board	Bent	\$ 2,670.60	\$ 2,670.60
1 pc	Sticker 'TOYOTA'	Essential	\$ 96.60	\$ 96.60
1 pc	Sticker 'DYNA'	Essential	\$ 31.90	\$ 31.90
2 pcs	Rear number plate lamp	cracked	\$ 76.20	\$ 76.20
2 pcs	Rear number plate panel	bent	\$ 100.00	\$ 100.00
2 pcs	Taillamps	Base cracked	\$ 425.00	\$ 425.00
2 pcs	Taillamp brackets	Dent/distorted	\$ 234.00	\$ 234.00
1pc	Exhaust silencer	Bent/distorted	\$ 547.50	\$ 547.50
1pc	Exhaust silencer rubber	Bent/deformed	\$ 35.00	\$ 35.00
Parts Sub-Total			\$ 6,467.70	\$ 6,467.70
Discount 25.00%			\$ 1,616.93	\$ 1,616.93
			\$ 4,850.78	\$ 4,850.78

Vehicle Number : GBB9329J

SPARE PARTS


QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>Special Nett Items</i>				
1pc	Sticker '70KM/H'	Essential	\$ 35.00	\$ 35.00
1 pc	Rear number plate	damaged	\$ 65.00	\$ 65.00
1 set	Reverse sensor	Shocked	\$ 280.00	\$ 250.00
Special Nett Sub-Total			\$ 380.00	\$ 350.00
Spare Parts Total			\$ 5,230.78	\$ 5,200.78

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare PartsTotal c/f	\$ 5,230.78	\$ 5,200.78
1	Labour charges to repair and panel beat the tailboard lower support, rear cargo deck and replace the above mentioned parts.	\$ 1,600.00	\$ 1,400.00
2	To check wiring functions & conduct water leakage test.	\$ 180.00	\$ 150.00
3	To putty, apply primer & spray-paint the affected areas.	\$ 1,600.00	\$ 1,400.00
5	To apply rust-proofing on repaired/replaced panels.	\$ 180.00	\$ 150.00
6	To remove and replace reverse sensor	\$ 180.00	\$ 150.00
	Total	\$ 8,970.78	\$ 8,450.78

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 7,300.00


Fong Kok Heng
Qualified Appraiser

