

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 13 Apr 2021

Preliminary Advice

Insured Vehicle No	: GBH5844H	Accident Date	: 01/12/2020
TP Vehicle No	: SH2807J	Assignment Date	: 03/12/2020
Make	: TOYOTA COROLLA	Est. Duration of Repair	: 8
Date of Inspection	: 14/12/2020		
Inspection At	: HUA MENG SPRAY PAINTING WORKSHOP (HQ) NO 1 KAKI BUKIT AVENUE 6, #01-61 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,497.50
Revised Amount	:S\$	6,908.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,908.80
Lump Sum Repair	:S\$	5,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- ☐ The vehicle is economical for repair
- ☐ The vehicle is not economical for repair
- ☐ Part-by-Part repair
- ☒ Lump Sum repair

- ☒ The above survey was conducted on a 'without prejudice' basis.