

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20013343/AQF3E2
Date: 30/12/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993762	
Claimant Vehicle No :	SLS3196G	Insured Vehicle No :	SMV769X	
Date of Loss:	30/11/2020	Nature of Claim:	TP	Claim No: 7490014156SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS3196G		
Make & Model:	TOYOTA PREVIA, 2.4 7-seater (A)	Engine No:	2AZH485228
Reg. Date:	03/05/2010 (Man. Year: 2010)	Chassis No:	JTEGD52M707087544
Colour:	Grey	Odometer:	144081 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,519.54	1,637.14	3,882.40	70.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	630.00	1,070.00	62.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,219.54	2,267.14	4,952.40	68.60
Approved Total (Overridden) (S\$)		1,800.00		
Nett Amount (S\$)	7,219.54	1,800.00	5,419.54	75.07

INSPECTION

Date of Assignment:	03/12/2020		
Date Inspected:	07/12/2020	Inspected At:	1 Kaki Bukit Ave 6 #02-39 Blk A Autobay@Kaki Bukit
Estimated Period of Repair:	3.0 days		Repairer : DC'S Automotive Pte Ltd

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	872.90 FL	*872.90 FL
2	1		*FRONT BUMPER FOG LAMP - LH	Cracked	381.60 FL	*275.00 FL
3	1		*FRONT BUMPER SPONGE	Not Necessary	182.60 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	571.26 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINERS - L/R	N/S Damaged	179.90 FL	*89.95 FL
6	1		*FRONT BUMPER LOGO	Not Necessary	68.60 FL	*- FL
7	1		*FRONT FENDER - LH	Not Necessary	811.35 FL	*- FL
8	1		*FRONT FENDER INNER SHIELD - LH	Not Necessary	289.91 FL	*- FL
9	1		*FRONT HEADLAMP - LH	Cracked	2,893.65 FL	*905.00 FL
10	1		*FRONT GRILLE	Not Necessary	580.95 FL	*- FL
11	1		*SET FRONT BUMPER PDC SENSOR	Not Necessary	350.00 FS	*- FS
12	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
					Sub Total (\$\$)	7,227.722,172.85
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,708.18535.71
					Total Parts (\$\$)	5,519.541,637.14

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	30.00
2	TO RESPRAY UNDERCOATING	New	50.00	0.00
3	TO RESPRAY PAINTING AND ETC	New	800.00	250.00
4	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	800.00	350.00
Gross Labour Cost (\$\$)			1,700.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >