

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013349/EQF3E2

Date: 23/12/2020

REFERENCE

Insured/Claimant:	PHAY SU ING, VALERIE	Policy No:	2070153500		
Date of Loss:	02/12/2020	Nature of Claim:	OD	Claim No:	9361861635SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW676A		
Make & Model:	KIA NIRO, 1.6 HYBRID GDI DCT SUNROOF (A)	Engine No:	G4LEKS616368
Reg. Date:	30/10/2020 (Man. Year: 2019)	Chassis No:	KNACB81CVL5371487
Colour:	Red	Odometer:	1800 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	S\$85,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,086.80	1,566.40	520.40	24.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,230.00	3,390.00	1,840.00	35.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,316.80	4,956.40	2,360.40	32.26
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	6,716.80	4,356.40	2,360.40	35.14
+ GST 7.00/7.00% (S\$)	470.18	304.95	165.23	35.14
Nett Amount (S\$)	7,186.98	4,661.35	2,525.63	35.14

INSPECTION

Date of Assignment:	03/12/2020		
Date Inspected:	03/12/2020	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	7.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*PANEL ASSY-BACK	Repair	526.00 FL	*- FL
3	1		*COVER-RR BUMPER, UPR	Crushed	486.00 FL	*486.00 FL
4	1		*COVER-RR BUMPER, LWR	Broken	392.00 FL	*392.00 FL
5	1		*COVER-RR BUMPER SIDE UNDER, LH	Broken	12.00 FL	*12.00 FL
6	1		*MOULDING ASSY-RR BUMPER SIDE ,L	Not Necessary	15.00 FL	*- FL
7	1		*MOULDING ASSY-RR BUMPER SIDE ,R	Not Necessary	15.00 FL	*- FL
8	1		*COVER-RR REFLECTOR, LH	Cut	51.00 FL	*51.00 FL
9	1		*LAMP ASSY-REAR FOG & R/REFL, LH	Cut	364.00 FL	*364.00 FL
10	1		*COVER-RR BUMPER SIDE UNDER, RH	Not Necessary	12.00 FL	*- FL
11	1		*BRACKET-RR BEAM UPR MTG, LH	Not Necessary	5.00 FL	*- FL
12	2		*BRACKET-RR BEAM LWR MTG, LH	Not Necessary	10.00 FL	*- FL
13	1		*BRACKET-RR BEAM UPR MTG, RH	Not Necessary	5.00 FL	*- FL
14	1		*BEAM-RR BUMPER	Broken	261.00 FL	*261.00 FL
15	1		*STAY-RR BUMPER LH	Bent	67.00 FL	*67.00 FL
16	1		*STAY-RR BUMPER RH	Bent	67.00 FL	*67.00 FL
17	1		*BRACKET ASSY-RR BUMPER SIDE, LH	Broken	25.00 FL	*25.00 FL
18	1		*BRACKET ASSY-RR BUMPER SIDE, RH	Not Necessary	25.00 FL	*- FL
19	1		*EMBLEM - NIRO	Necessary	25.00 FL	*25.00 FL
20	1		*LOGO-KIA	Necessary	42.00 FL	*42.00 FL
21	1		*EMBLEM-ECO HYBRID	Necessary	29.00 FL	*29.00 FL
22	1		*SKID PLATE-RR BUMPER	Crushed	98.00 FL	*98.00 FL
23	10		*CLIP (Supplementary)	Necessary	10.00 FL	*10.00 FL
24	2		*NUT-PLUG (Supplementary)	Necessary	4.00 FL	*4.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,596.00	1,953.00
- List Item Discount on L Items 20.00/20.00% (\$)	509.20	386.60
Total Parts (\$)	2,086.80	1,566.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER, END PANEL & AFFECTED AREA REPAIR ON REAR TAILGATE & REAR LH FENDER	New	2,000.00	800.00
2	PAINT WORK ON REAR BUMPER, TAILGATE, END PANEL & REAR LH FENDER	New	1,920.00	1,440.00
3	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	120.00
4	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	0.00
5	TO APPLY SEALANT ON AFFECTED AREA	New	40.00	0.00
6	PERFORM RUST PREVENTION	New	40.00	40.00
7	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	TO SUPPLY C & C EMBLEM	New	40.00	40.00
10	TO SUPPLY REAR NUMBER PLATE WITH FRAME	New	50.00	50.00
11	REPAIR END PANEL (Supplementary)	New	400.00	400.00
12	SPRAY PAINT END PANEL (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$\$)			5,230.00	3,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >