



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 6987C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	BUCKLED	1,074.80	1,074.80
1	REAR BUMPER RH REFLECTOR	SERVICEABLE	68.40	-
1	REAR BUMPER TOW COVER	MISSING	36.20	36.20
2	REAR BUMPER SIDE RETAINER	SERVICEABLE	92.20	-
1	REAR BUMPER INNER REINFORCEMENT	BENT	537.30	537.30
1	SET REAR BUMPER CLIPS	NECESSARY	40.00	40.00
1	REAR BOOT LID	BENT / BUCKLED	957.40	957.40
1	REAR BOOT CENTRE "MAZDA" LOGO	NECESSARY	74.40	74.40
1	REAR BOOT RH "SKYACTIV" EMBLEM	NECESSARY	63.60	63.60
1	REAR BOOT LH "MAZDA 3" EMBLEM	NECESSARY	53.40	53.40
1	REAR BOOT RH REFLECTOR/LAMP	SCRATCHED	345.70	345.70
1	REAR END PANEL	TO REPAIR SEE LABOUR	605.10	-
1	REAR END PANEL TOP GARNISH	MTG CRACKED	105.10	105.10
	LESS 20% DISCOUNT		-810.72	-657.58
			3,242.88	2,630.32
1	REAR BOOT WEATHERSTRIP (50%)(SN)	CUT	193.40	96.70
	LESS 20% DISCOUNT		-38.68	-
			154.72	96.70
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REVERSE SENSORS (SN)	SHORTED	250.00	200.00
1	SET REAR END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
			330.00	200.00
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES FOR REMOVE/REFIT,CUTTING/WELDING AND REPLACEMENT OF DAMAGES.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,000.00	500.00
	TO PUTTY AND SPRAY SPRAY PAINTINGS CHARGES.		1,000.00	660.00
	TO CHECK WIRINGS AND LIGHTINGS.		40.00	20.00

Report Ref No. CS/SMO20013351/Kqd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE,REFIT REVERSES SENSORS.		80.00	50.00
	TO REMOVE,REFIT REAR BOOTLID FITTINGS.		80.00	50.00
	TO REMOVE,REFIT REAR UPHOLSTERY AND ATTACHMENTS.		120.00	40.00
	TO SUPPLY AND APPLY ANTI RUST TREATMENT.		80.00	30.00
			2,400.00	1,350.00
<b>GRAND TOTAL</b>			<b>6,127.60</b>	<b>4,277.02</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,400.00</b>

Report Ref No. CS/SMO20013351/Kqd3n2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.