

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG20013353/UGA3Q2

Date:

30/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : PC8042X

Date of Loss: 29/11/2020

Policy No:

1700073560

Insured Vehicle No :

GBG8126H

Nature of Claim:

TP

Claim No:

3334858793SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC8042X**

Make & Model: TOYOTA HIACE, 3.0 D HIGH ROOF COMMUTER TURBO (A)

Reg. Date: 25/01/2019 (Man. Year: 2018)

Colour: Silver

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1KD2828426

Chassis No: JTFST22P500038191

Odometer: 37275 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15

Front Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Tyre Size:

195R15

Rear Left Side:

Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,054.30	9,172.91	7,881.39	46.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,470.00	1,980.00	490.00	19.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,524.30	11,152.91	8,371.39	42.88
Approved Total (Overridden) (S\$)		8,900.00		

(S\$)	19,524.30	8,900.00	10,624.30	54.42
+ GST 7.00/7.00% (S\$)	1,366.70	623.00	743.70	54.42
Nett Amount (S\$)	20,891.00	9,523.00	11,368.00	54.42
+ Loss of Use (7.0 x S\$90.00/day) (S\$)		630.00		
Nett Liability (S\$)		10,153.00		
Global Sum Settlement (S\$)		10,000.00		

INSPECTION

Date of Assignment: 04/12/2020

Date Inspected: 04/12/2020

Inspected At:

V-tec Asia Automotive Pte Ltd (HQ)

8 KAKI BUKIT AVE 4, #07-08/09 PREMIER@KB

Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ORIGINAL NEW	Distorted	1,500.00 F	*661.10 FL
2	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	160.00 F	*- FL
3	1		*FRONT BUMPER GRILLE	Torn	450.00 F	*274.75 FL
4	1		*RADIATOR GRILLE INNER	Broken	450.00 F	*394.00 FL
5	1		*RADIATOR UPPER GRILLE	Broken	490.00 F	*366.20 FL
6	1		*RADIATOR LOWER GRILLE	Broken	450.00 F	*313.50 FL
7	1		*FRONT BONNET ORIGINAL NEW	Distorted	850.00 F	*844.10 FL
8	1		*FRONT SIDE PANEL RH & LH	N/S Dented	360.00 F	*180.00 FL
9	2		*FRONT HEADLIGHT ORIGINAL	Cracked	1,416.20 F	*1,416.20 FL
10	1		*CARPLATE	Bent	80.00 FS	*15.00 FS
11	1		*CARPLATE HOLDER	No such part	50.00 F	*- FL
12	1		*TOYOTA LOGO	Necessary	80.00 F	*68.10 FL
13	1		*WIPER COVER	Deformed	220.00 F	*220.00 FL
14	1		*WHETHER STRIP COVER	Torn	380.00 F	*266.30 FL
15	1		*FRONT BUMPER REINFORCEMENT	Distorted	950.00 F	*397.10 FL
16	1		*FRONT BUMPER COVER SUPPORT RH & LH	N/S Distorted	390.00 F	*145.00 FL
17	1		*REINFORCEMENT SUB-ASSY TOP	Distorted	475.00 F	*281.10 FL
18	2		*SIDE FENDER BRACKETS	No such part	180.00 F	*- FL
19	1		*RADIATOR ASSY	Punctured	1,617.10 F	*1,617.10 FL
20	1		*INTERCOOLER ASSY	Dented / Punctured	950.00 F	*950.00 FL
21	1		*AIR CON CONDENSER	Punctured	1,216.00 F	*1,216.00 FL
22	1		*A/C HIGH PRESSURE PIPE	Not Necessary	350.00 F	*- FL
23	1		*A/C LOW PRESSURE PIPE	Not Necessary	330.00 F	*- FL
24	1		*WIPER TANK	Distorted	240.00 F	*240.00 FL
25	1		*WIPER TANK MOTOR	Not Necessary	280.00 F	*- FL
26	1		*AIR FAN COVER ASSY	Cracked	395.00 F	*395.00 FL
27	1		*CRASH SENSOR LH SIDE	Cracked	360.00 F	*360.00 FL
28	1		*DOOR HINGE	Not Necessary	495.00 F	*- FL
29	1		*SPARE TANK	Cracked	225.00 F	*225.00 FL
30	1		*BUMPER BRACKETS	N/S Cracked	180.00 F	*90.00 FL
31	2		*BONNET	Bent / Twisted	220.00 F	*220.00 FL
32	1		*DUCT ASSY AIR VENT	Torn	180.00 F	*180.00 FL
33	1		*AIR BLOWER GUN	Not Necessary	150.00 F	*- FL
34	1		*BONNET LOCK	Twisted	180.00 F	*180.00 FL
35	1		*FAN COWLING	Cracked	280.00 F	*280.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*BRACE PANEL	Twisted	95.00 F	*95.00 FL
37	1		*SUPPORT PANEL	Distorted	295.00 F	*295.00 FL
38	1		*RADIATOR COOLANT	Necessary	85.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)**17,054.30****12,215.55****- List Item Discount on L Items 0.00/25.00% (S\$)**

0.00

3,042.64

Total Parts (S\$)**17,054.30****9,172.91**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RESPRAY TO BRAND NEW FRONT BUMPER ,FRONT BONNET & FRONT SIDE FENDER RH & LH SIDE	New	1,190.00	1,100.00
2	DIAGNOSTIC TO VEHICLE ELECTRICAL SYSTEM AND FRONT HEADLIGHT RH & LH SIDE	New	250.00	30.00
3	LABOUR FOR REMOVE/INSTALLATION OF REPLACED PARTS ,FRONT LH HEADLAMP ,FRONT BUMPER ,FRONT SIDE FENDER RH & LH ,FRONT HEADLIGHT RH & LH SIDE ,RADIATOR & AIRCON CONDENSER WHETHER STRIP ,TOYOTA LOGO ,RADIATOR UPPER GRILLE ,RADIATOR LOWER GRILL ,BUMPER GRILL,CARPLATE & HOLDER AND ETC	New	980.00	800.00
4	AIR CON GAS R134A	New	50.00	50.00
Gross Labour Cost (S\$)			2,470.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >