

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG20013354/AVF3E2

Date: 16/04/2021

REFERENCE

Insured/Claimant:	GUO YA WEN	Policy No:	2070138029		
Date of Loss:	28/11/2020	Nature of Claim:	OD	Claim No:	0639900265SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU1088B		
Make & Model:	AUDI A6, 1.8 TFSI S-tronic (A)	Engine No:	DKY013858
Reg. Date:	24/09/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF26LN056216
Colour:	Black	Odometer:	1581 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$185,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,269.00	2,811.20	3,457.80	55.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,952.00	2,127.00	1,825.00	46.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,221.00	4,938.20	5,282.80	51.69
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	8,621.00	3,338.20	5,282.80	61.28
+ GST 7.00/7.00% (S\$)	603.47	233.67	369.80	61.28
Nett Amount (S\$)	9,224.47	3,571.87	5,652.60	61.28

INSPECTION

Date of Assignment:	04/12/2020		
Date Inspected:	04/12/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,639.00 FS	*2,111.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	234.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	875.00 FS	*700.00 FS
4	1		*REAR BUMPER TRIM - RH	Not Necessary	242.00 FS	*- FS
5	1		*REAR BUMPER TRIM - CENTRE	Not Necessary	171.00 FS	*- FS
6	1		*REAR BUMPER SECURING STRIP	Not Necessary	170.00 FS	*- FS
7	1		*TELEPHONE AERIAL	Not Necessary	178.00 FS	*- FS
8	1		*REAR LIGHT REFLECTOR - RH OUTER	Not Necessary	41.00 FS	*- FS
9	1		*REAR LIGHT REFLECTOR - RH INNER	Not Necessary	30.00 FS	*- FS
10	1		*REAR BUMPER CARRIER	Not Necessary	915.00 FS	*- FS
11	2		*REAR BUMPER CARRIER SEAL - LH / RH	Not Necessary	28.00 FS	*- FS
12	1		*REAR BUMPER GUIDE SECTION - RH LOWER	Not Necessary	63.00 FS	*- FS
13	1		*REAR BUMPER GUIDE SECTION - RH UPPER	Not Necessary	45.00 FS	*- FS
14	1		*REAR BUMPER HOLDING STRAP - CENTRE	Not Necessary	116.00 FS	*- FS
15	1		*REAR BUMPER GUIDE PROFILE - RH	Not Necessary	66.00 FS	*- FS
16	1		*REAR PARKING AID SENSOR	Not Necessary	242.00 FS	*- FS
17	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
18	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	6,269.00 2,811.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER	New	1,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO REPAIR RHS TAILLAMP PANEL (Supplementary)	New	400.00	250.00
6	TO RESPRAY RHS TAILLAMP PANEL (Supplementary)	New	800.00	275.00
Gross Labour Cost (\$\$)			3,952.00	2,127.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >