



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YL 7733M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE ALUMINIUM (SN)	DENTED / BENT	3,500.00	1,500.00
1	TAILGATE ALUMINIUM SIDE BRACKET O/S (SN)	BENT	250.00	100.00
1	TAILGATE LOWER MEMBER (SN)	TO REPAIR SEE LABOUR	800.00	-
1	TAILGATE LOWER 'L' BRACKET O/S (SN)	TO REPAIR SEE LABOUR	150.00	-
1	TAILGATE 'L' BRACKET REBBER O/S (SN)	MISSING	60.00	30.00
1	TAILGATE HINGE O/S (SN)	TO REPAIR SEE LABOUR	180.00	-
1	TAILGATE '18 PAX' STICKER (SN)	NECESSARY	20.00	10.00
1	TAILGATE '60KM/H' STICKER (SN)	NECESSARY	20.00	10.00
1	DROPSIDE GATE ALUMINIUM O/S (SN)	DISTORTED	5,200.00	2,800.00
1	DROPSIDE GATE ALUMINIUM BRACKET O/S (SN)	BENT	250.00	100.00
1	REAR SAFETY BAR (SN)	NOT NECESSARY	1,200.00	-
			11,630.00	4,550.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	80.00	-
	TO DISMANTLE & REFIX REAR CARGO DECK.	NOT NECESSARY	680.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF TAILGATE LOWER MEMBER, TAILGATE LOWER 'L' BRACKET O/S AND TAILGATE HINGE O/S.		800.00	380.00
	TO PUTTY & SPRAY PAINTING.		1,200.00	700.00
			2,810.00	1,100.00
	GRAND TOTAL		14,440.00	5,650.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,500.00
---	--	--	-----------------

Report Ref No. CS/SMO20013356/Utd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.