

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III20013358/DGS3Q2**Date:** 13/01/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	-
<b>Claimant Vehicle No :</b>	SH6983G	<b>Insured Vehicle No :</b>	YN7388R
Date of Loss:	24/11/2020	Nature of Claim:	TP
		Claim No:	MCV2020D0002531

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SH6983G</b>	Engine No:	2ZRS066831
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU503565194
Reg. Date:	06/10/2017 (Man. Year: 2017)	Odometer:	477839 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	46,732.62	25,422.72	21,309.90	45.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,120.00	3,230.00	1,890.00	36.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>51,852.62</b>	<b>28,652.72</b>	<b>23,199.90</b>	<b>44.74</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>22,900.00</b>		
<b>(S\$)</b>	51,852.62	22,900.00	28,952.62	55.84
<b>+ GST 7.00/7.00% (S\$)</b>	3,629.68	1,603.00	2,026.68	55.84
<b>Nett Amount (S\$)</b>	<b>55,482.30</b>	<b>24,503.00</b>	<b>30,979.30</b>	<b>55.84</b>
<b>+ Car Rental (37.0 x S\$125.40/day) (S\$)</b>		4,639.80		
<b>+ Other Costs (S\$)</b>		80.00		
<b>Nett Liability (S\$)</b>		<b>29,222.80</b>		
<b>Global Sum Settlement (S\$)</b>		<b>29,000.00</b>		

INSPECTION

Date of Assignment:	04/12/2020	
Date Inspected:	04/12/2020 Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	21.0 days	

**Adjuster:** BRYAN TANI**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2021)
<b>Parts:</b> 144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SH6983G)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID COVER	Buckled	1,126.60 FL	*1,126.60 FL
2	1		*REAR TRUNK LID LOCK	Damaged	457.90 FL	*457.90 FL
3	1		*REAR TRUNK LID COVER TRIM BOARD	Mtg Broken	216.50 FL	*216.50 FL
4	1		*BOOT LID TRIMBOARD CENTRE	Broken	159.60 FL	*159.60 FL
5	2		*BOOT LID TRIMBOARD SIDE (LH/RH)	Broken / Deformed	185.00 FL	*185.00 FL
6	1		*BOOT LID TRIMBOARD REAR	Not Necessary	124.80 FL	*- FL
7	1		*BOOT HANDLE	Not Necessary	31.80 FL	*- FL
8	1		*REAR TRUNK LID RUBBER	Deformed	365.20 FL	*365.20 FL
9	1		*REAR TRUNK LID GLASS (BLACK COLOR)	Broken	969.70 FL	*969.70 FL
10	1		*BOARD ASSY ,BACK DOOR TRIM	Not Necessary	354.40 FL	*- FL
11	1		*GARNISH SUB-ASSY ,BACK DOOR OUTSIDE	Broken	896.30 FL	*896.30 FL
12	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	60.80 FL	*60.80 FL
13	1		*REAR TRUNK LID LOGO (HYBRID)	Necessary	52.40 FL	*52.40 FL
14	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Necessary	52.90 FL	*52.90 FL
15	1		*THIRD BRAKE LIGHT	Broken	394.70 FL	*394.70 FL
16	1		*REAR TRUNK LID STRIKER	Bent	98.70 FL	*98.70 FL
17	2		*REAR TRUNK LID HINGE (LH/RH)	Bent	379.00 FL	*379.00 FL
18	2		*REAR TRUNK LID ABSORBER (LH/RH)	Bent	575.00 FL	*575.00 FL
19	2		*REAR TRUNK LID ABSORBER BRACKET (LH/RH)	Not Necessary	255.80 FL	*- FL
20	2		*REAR TRUNK LID STOPPER (LH/RH)	Not Necessary	169.60 FL	*- FL
21	1		*SPOILERSUB-ASSY ,REAR	Broken	953.70 FL	*953.70 FL
22	1		*REAR WINDSCREEN GLASS W/MOULDING	Broken	1,778.30 FL	*1,778.30 FL
23	1		*ROOF TOP CENTER COVER -BLACK	Dislodged	956.30 FL	*956.30 FL
24	1		*ROOF TOP GARNISH SUB LH	Dislodged	136.80 FL	*136.80 FL
25	1		*ROOF TOP GARNISH SUB RH	Dislodged	136.80 FL	*136.80 FL
26	1		*COVER ASSY TONNEAU	Not Necessary	923.40 FL	*- FL
27	1		*PLATE REAR WHEEL HOUSE ,FRONT RH	Not Necessary	57.50 FL	*- FL
28	1		*PLATE REAR WHEEL HOUSE ,FRONT LH	Not Necessary	57.50 FL	*- FL
29	1		*MOTOR ASSY ,REAR WIPER	Bent	734.60 FL	*734.60 FL
30	1		*ARM ASSY ,REAR WIPER	Not Necessary	84.70 FL	*- FL
31	1		*BLADE ASSY ,REAR WIPER	Not Necessary	55.00 FL	*- FL
32	1		*REAR BUMPER	Buckled	458.60 FL	*458.60 FL
33	1		*REAR BUMPER REINFORCEMENT	Dented	318.80 FL	*318.80 FL
34	1		*REAR BUMPER LOWER COVER	Dented	552.60 FL	*552.60 FL
35	1		*REAR BUMPER SIDE RETAINER	Broken	112.70 FL	*112.70 FL
36	1		*REAR BUMPER TOWING COVER	Dislodged	82.70 FL	*82.70 FL
37	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
38	2		*REAR BUMPER UPPER STOPPER (LH/RH)	Not Necessary	152.80 FL	*- FL
39	1		*ARM SUB-ASSY ,REAR BUMPER ,RH	Not Necessary	139.60 FL	*- FL
40	1		*REAR BUMPER UNDER SIDE COVER (RH)	Broken	232.00 FL	*232.00 FL
41	1		*SEAL ,REAR BUMPER SIDE ,RH	Bent	148.40 FL	*148.40 FL
42	1		*SEAL ,REAR BUMPER SIDE ,LH	Cut / Bent	148.40 FL	*148.40 FL
43	1		*REAR BUMPER UNDER SIDE COVER (LH)	Mtg Cracked	232.00 FL	*232.00 FL
44	1		*ARM SUB-ASSY ,REAR BUMPER ,LH	Not Necessary	139.60 FL	*- FL
45	2		*TAIL LAMP ASSY (UPPER) (LH/RH)	Broken	1,115.80 FL	*1,115.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	2		*TAIL LAMP ASSY (LOWER) (LH/RH)	Broken	1,096.80 FL	*1,096.80 FL
47	2		*TAIL LAMP QUARTER PANEL (LH/RH)	Buckled	432.00 FL	*432.00 FL
48	2		*TAIL LAMP SIDE COVER (LH/RH)	Cut / Deformed	512.00 FL	*512.00 FL
49	2		*REAR TAILLAMP GUIDE -WHITE (LH/RH)	Not Necessary	190.60 FL	*- FL
50	1		*REAR END PANEL	Buckled	602.10 FL	*602.10 FL
51	1		*REAR END PANEL GARNISH	Deformed	161.80 FL	*161.80 FL
52	1		*REAR WIRING ASSY	Wire Torn	582.40 FL	*582.40 FL
53	1		*REAR SPARE TYRE PANEL	Buckled	667.70 FL	*667.70 FL
54	1		*REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	Bent	101.40 FL	*101.40 FL
55	2		*REAR FIBER TOOL BOX TRIM (LH/RH)	Broken	1,196.00 FL	*1,196.00 FL
56	1		*REAR FIBER TOOL BOX CENTER	Not Necessary	186.20 FL	*- FL
57	1		*SPARE TYRE LOCK NUT	Broken	88.40 FL	*88.40 FL
58	1		*SPARE TYRE LOCK NUT BRACKET	Broken / Bent	113.50 FL	*113.50 FL
59	2		*SPARE TYRE SIDE PANEL (LH/RH)	Repair	393.00 FL	*- FL
60	1		*REAR EXHAUST PIPE	Dented	1,163.40 FL	*1,163.40 FL
61	1		*REAR EXHAUST PIPE HANGER	Not Necessary	40.70 FL	*- FL
62	1		*REAR EXHAUST PIPE INSULATOR	Bent	314.60 FL	*314.60 FL
63	1		*REAR FENDER ,RH	Buckled	836.70 FL	*836.70 FL
64	1		*REAR FENDER ,LH	Buckled	836.70 FL	*836.70 FL
65	2		*REAR FENDER INNER PANEL (LH/RH)	Repair	1,456.00 FL	*- FL
66	1		*REAR FENDER OUTER PANEL ,LH	Repair	486.00 FL	*- FL
67	1		*REAR FENDER REINFORCEMENT ,ROCKER PANEL LH	Not Necessary	552.30 FL	*- FL
68	1		*REAR FENDER PANEL,ROOF SIDE OUTER ,LH	Repair	311.00 FL	*- FL
69	1		*REAR FENDER EXTENSION ,ROOF SIDE INNER FRT ,LH	Not Necessary	265.10 FL	*- FL
70	1		*REAR FLOOR PANEL SIDE (LH)	Repair	276.20 FL	*- FL
71	1		*REAR FENDER OUTER PANEL ,RH	Repair	486.00 FL	*- FL
72	1		*REAR FENDEL PANEL ,ROOF SIDE OUTER ,RH	Not Necessary	311.00 FL	*- FL
73	1		*REAR FENDER REINFORCEMENT ,ROCKER PANEL ,RH	Not Necessary	552.30 FL	*- FL
74	1		*REAR FENDER EXTENSION ,ROOF SIDE INNER FRT RH	Not Necessary	265.10 FL	*- FL
75	1		*REAR FLOOR PANEL SIDE (RH)	Repair	276.20 FL	*- FL
76	2		*REAR FENDER SHIELD (LH/RH)	Not Necessary	348.40 FL	*- FL
77	2		*REAR FENDER TRIMBOARD (LH/RH)	Deformed	1,450.00 FL	*1,450.00 FL
78	2		*REAR FENDER TOP COVER (BLACK COLOR) (LH/RH)	Dislodged	602.20 FL	*602.20 FL
79	1		*REAR FENDER AIR DUCT (LH/RH)	N/S Deformed / O/SNotNecessary	330.20 FL	*165.10 FL
80	2		*REAR FENDER TOP PANEL INNER (LH/RH)	Repair	680.40 FL	*- FL
81	1		*REAR FLOOR PANEL SIDE (LH)	Repair	717.60 FL	*- FL
82	1		*REAR FLOOR PANEL SIDE (RH)	Buckled	717.60 FL	*717.60 FL
83	2		*REAR FLOOR UNDER COVER (LH/RH)	Not Necessary	1,693.60 FL	*- FL
84	1		*REAR FLOOR PANEL	Not Necessary	2,850.50 FL	*- FL
85	1		*REAR WINDSCREEN GLASS W/MOULDING	Repeated	1,778.30 FL	*- FL
86	1		*REAR WINDSCREEN SEALANT	Repeated	46.00 FL	*- FL
87	1		*PANEL SUB-ASSY ,REAR DOOR ,RH	Repair	1,258.30 FL	*- FL
88	1		*PANEL SUB-ASSY ,REAR DOOR ,LH	Repair	1,258.30 FL	*- FL
89	1		*REVERSE CAMERA ASSY	Not Necessary	380.00 FS	*- FS
90	1		*REAR TRUNK LOWER W/S MOULDING	Necessary	180.00 FS	*180.00 FS
91	1		*REAR LOWER W/S SEALANT	Necessary	46.00 FS	*46.00 FS
92	1		*REAR WINDSCREEN MOULDING	Not Necessary	160.00 FS	*- FS
93	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
94	1		*REAR NO.PLATE WITH COVER	Bent	45.00 FS	*45.00 FS
95	1		*REAR TRUNK LID APPS STICKER	Necessary	40.00 FS	*40.00 FS
96	1		*REAR TRUNK LID COMFORT & TEL NO.STICKER	Necessary	60.00 FS	*60.00 FS
97	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
98	1		*REAR BUMPER RUBBER MAT	Deformed	50.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
99	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
100	2		*REAR DOOR COMFORT & APPS STICKER (LH/RH)	Necessary	160.00 FS	*160.00 FS
101	2		*REAR DOOR ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
102	1		*REAR SEAT LOWER CUSHION (50%)	Bent / Deformed	2,488.00 FS	*1,555.00 FS
103	1		*FRONT CUSHION SEAT (50%)	Bent	944.00 FS	*590.00 FS
104	1		*ROOF PANEL	Repair	3,120.00 FL	*- FL
105	2		*REAR DOOR SAFETY BELT (LH/RH)	Activated	1,676.00 FL	*1,676.00 FL
106	1		*ROOF LINING	Crumpled / Bent	2,059.50 FL	*2,059.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>57,132.10</b>	<b>32,794.40</b>
<b>- List Item Discount on L Items 20.00/25.00% (S\$)</b>	10,399.48	7,371.68
<b>Total Parts (S\$)</b>	<b>46,732.62</b>	<b>25,422.72</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,800.00	1,500.00
2	SPRAY PAINTING CHARGE	New	1,600.00	1,400.00
3	WIRING CHARGE	New	180.00	30.00
4	TUFF KOTE	New	160.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE/REFIX EXHAUST PIPE	New	80.00	60.00
10	TRANSFER OF DOOR MECHANISM REAR	New	80.00	0.00
11	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
12	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
			<b>Gross Labour Cost (\$)</b>	<b>5,120.00</b>
				<b>3,230.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >