

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013374/EQD3E2
Date: 30/12/2020

REFERENCE

Insured/Claimant:	POH SIEW HWEE (FU XIUHUI)	Policy No:	1900084136	Claim No:	6905811827SG
Date of Loss:	02/12/2020	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK3117R	Engine No:	4J11AG9986
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	GF7W0600955
Reg. Date:	04/04/2019 (Man. Year: 2018)	Odometer:	44571 km
Colour:	Brown		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$95,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,072.02	1,901.11	170.91	8.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,000.00	880.00	46.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,952.02	2,901.11	1,050.91	26.59
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	3,652.02	2,601.11	1,050.91	28.78
+ GST 7.00/7.00% (S\$)	255.64	182.08	73.56	28.77
Nett Amount (S\$)	3,907.66	2,783.19	1,124.47	28.78

INSPECTION

Date of Assignment: 04/12/2020

Date Inspected:	04/12/2020	Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
Estimated Period of Repair:	3.0 days		209 Pandan Gardens
			Singapore 609339

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE,FR BUMPER	Broken	859.00 FL	*859.00 FL
2	1		*EXTENSION,FR BUMPER	Cut	515.00 FL	*515.00 FL
3	1		*COVER,FR BUMPER	Broken	359.00 FL	*359.00 FL
4	1		*RH GARNISH,FR BUMPER SIDE	Not Necessary	48.00 FL	*- FL
5	1		*RH GARNISH,FR BUMPER SIDE	Cracked	220.00 FL	*220.00 FL
6	1		*RH GARNISH,FR BUMPER SIDE	Not Necessary	112.00 FL	*- FL
7	1		*REINFORCEMENT,FR BUMPER	Bent	490.00 FL	*490.00 FL
8	1		*GARNISH,FR LICENSE PLATE	Not Necessary	23.00 FL	*- FL
9	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
					Sub Total (\$\$)	2,676.00
					- List Item Discount on L Items 23.00/23.00% (\$\$)	603.98
					Total Parts (\$\$)	2,072.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT BUMPER FACE.FRONT REINFORCEMENT	New	900.00	450.00
2	PAINT WORK SPRAY FRONT BUMPER FACE AND AFFECTED PORTION	New	700.00	350.00
3	SUPPLY FRONT NUMBER PLATE WITH FRAME	New	50.00	50.00
4	RE-APPLY ZERTONA COATING ON AFFECTED PORTION	New	80.00	-
5	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (\$\$)			1,880.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >