

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013389/KPS3Q2
Date: 26/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070030356
Claimant Vehicle No :	SKK4796Y	Insured Vehicle No :	SMS8453U
Date of Loss:	01/12/2020	Nature of Claim:	TP
		Claim No:	0157832546SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK4796Y		
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI 1623Q5 (A)	Engine No:	CAXD21933
Reg. Date:	22/07/2013 (Man. Year: 2013)	Chassis No:	WVWZZZ16ZDM074179
Colour:	Metallic Brown	Odometer:	81103 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,664.85	174.24	2,490.61	93.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	860.00	490.00	370.00	43.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,524.85	664.24	2,860.61	81.16
+ GST 7.00/7.00% (S\$)	246.74	46.50	200.24	81.15

Nett Amount (S\$)	3,771.59	710.74	3,060.85	81.16
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		892.74		

INSPECTION

Date of Assignment: 04/12/2020

Date Inspected: 10/12/2020

Inspected At:

Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
 Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR ARM RH	Serviceable	390.05 FL	*- FL
2	1		*SIDE MIRROR COVER RH	Serviceable	197.25 FL	*- FL
3	1		*SIDE MIRROR GLASS RH	Cracked	193.60 FL	*193.60 FL
4	1		*SIDE MIRROR SIGNAL LAMP RH	Serviceable	102.30 FL	*- FL
5	1		*FRONT DOOR RH	Repair	1,963.45 FL	*- FL
6	1		*FRONT DOOR RUBBER (AT DOOR)	Not Necessary	114.30 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,960.95	193.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	296.10	19.36
Total Parts (\$\$)	2,664.85	174.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR	New	60.00	40.00
2	TO DISMANTLE ALL DAMAGED PARTS ,TO CUT & WELD ,TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	400.00	200.00
3	TO SPRAY FRONT DOOR RH ,SIDE MIRROR RH	New	400.00	250.00
Gross Labour Cost (\$\$)			860.00	490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >