

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013392/EVF3E2

Date: 22/12/2020

REFERENCE

Insured/Claimant:	NG WEI LING, ROSALYN	Policy No:	1900163822		
Date of Loss:	04/12/2020	Nature of Claim:	OD	Claim No:	1427538432SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP2720D	Engine No:	3A92UJB1447
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AKH003367
Reg. Date:	19/09/2019 (Man. Year: 2019)	Odometer:	15646 km
Colour:	Red		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$57,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,454.72	7,855.46	1,599.26	16.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,385.00	4,055.00	2,330.00	36.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,839.72	11,910.46	3,929.26	24.81
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	15,239.72	11,310.46	3,929.26	25.78
+ GST 7.00/7.00% (S\$)	1,066.78	791.73	275.05	25.78
Nett Amount (S\$)	16,306.50	12,102.19	4,204.31	25.78

INSPECTION

Date of Assignment: 07/12/2020

Date Inspected: 07/12/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ,HEADLAMP SUPPORT UPR	Not Necessary	65.00 FL	*- FL
2	1		*PANEL ASSY ,FR END	Dented	1,055.00 FL	*1,055.00 FL
3	1		*CONDENSER ASSY ,A/C REFRIGE	Bent	758.00 FL	*758.00 FL
4	1		*PANEL ,AIR GUIDE	Broken	112.00 FL	*112.00 FL
5	1		*RADIATOR ASSY	Broken	967.00 FL	*967.00 FL
6	1		*FAN ,COOLING ,LH	Broken	77.00 FL	*77.00 FL
7	1		*SHROUD ,COOLING FAN	Broken	130.00 FL	*130.00 FL
8	1		*MOTOR COOLING FAN	Not Necessary	479.00 FL	*- FL
9	1		*TANK ASSY ,RADIATOR COND	Crushed	42.00 FL	*42.00 FL
10	1		*LLC	Necessary	26.00 FL	*26.00 FL
11	1		*PANEL ,AIR GUIDE ,RH	Broken	11.00 FL	*11.00 FL
12	1		*PANEL ,AIR GUIDE ,LH	Broken	11.00 FL	*11.00 FL
13	1		*HEADLAMP ASSY ,LH	Broken	660.00 FL	*660.00 FL
14	1		*HEADLAMP ASSY ,RH	Broken	660.00 FL	*660.00 FL
15	1		*GRILLE ,RADIATOR	Broken	554.00 FL	*554.00 FL
16	1		*MARK,THREE-DIA	Necessary	69.00 FL	*69.00 FL
17	1		*BRACKET ,FR BUMPER ,LH	Broken	13.00 FL	*13.00 FL
18	1		*BRACKET ,FR BUMPER ,RH	Broken	13.00 FL	*13.00 FL
19	1		*GRILLE ,FR UNDER	Broken	165.00 FL	*165.00 FL
20	1		*GARNISH ,FR BUMPER ,LH	Not Necessary	127.00 FL	*- FL
21	1		*GARNISH ,FR BUMPER ,RH	Not Necessary	127.00 FL	*- FL
22	1		*COVER ,HEADLAMP SUPT PANEL	Broken	62.00 FL	*62.00 FL
23	10		*CLIP,FR BUMPER	Necessary	40.00 FL	*40.00 FL
24	1		*FACE ,FR BUMPER	Dented	703.00 FL	*703.00 FL
25	1		*BODY KIT ,ATTRAGE	Deformed / Cut	1,643.00 FS	*1,643.00 FS
26	1		*LATCH ,HOOD	Not Necessary	69.00 FL	*- FL
27	6		*CLIP ,HOOD INSULATOR	Not Necessary	18.00 FL	*- FL
28	1		*INSULATOR ,HOOD	Not Necessary	177.00 FL	*- FL
29	1		*HINGE ,HOOD, RH	Not Necessary	56.00 FL	*- FL
30	1		*HINGE ,HOOD, LH	Not Necessary	56.00 FL	*- FL
31	1		*HOOD	Repair	734.00 FL	*- FL
32	1		*FENDER ,FR LH	Dented	497.00 FL	*497.00 FL
33	1		*FENDER ,FR RH	Dented	497.00 FL	*497.00 FL
34	2		*EMBLEM ECO	Necessary	34.00 FS	*34.00 FS
35	1		*LH GARNISH ,FR FENDER	Not Necessary	65.00 FL	*- FL
36	1		*RH GARNISH ,FR FENDER	Not Necessary	65.00 FL	*- FL
37	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
38	1		*COVER, FR BUMPER (SUPPLEMENTARY)	Crushed	13.00 FL	*13.00 FL
39	1		*OIL COOLER ASSY,A/T (SUPPLEMENTARY)	Bent	558.00 FL	*558.00 FL
40	1		*PIPE, A/C CONDENSER OUTLET (SUPPLEMENTARY)	Bent	305.00 FL	*305.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,763.00	9,695.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	2,308.28	1,839.54
Total Parts (\$\$)	9,454.72	7,855.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL,FRONT BONNET ,FRONT BUMPER ,FRONT BODY KITS, RH FRONT FENDER ,LH FRONT FENDER	New	2,250.00	900.00
2	REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK	New	100.00	100.00
3	TOP UP AIR CON GAS AND CHECK A/CON SYSTEM	New	80.00	80.00
4	PAINT WORK SPRAY FRONT SUPPORT PANEL,FRONT BONNET ,FRONT BUMPER ,FRONT BODY KITS, RH FRONT FENDER ,LH FRONT FENDER AND AFFECTED PORTION	New	2,450.00	1,750.00
5	APPLY BODY SEALANT	New	160.00	0.00
6	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	PERFORM RUST PREVENTION	New	120.00	0.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	SUPPLY FRONT NUMBER PLATE WITH FRAME	New	50.00	50.00
10	RENEW FRONT SUPPORT PANEL	New	675.00	675.00
11	SPRAY PAINT FRONT SUPPORT PANEL	New	350.00	350.00
Gross Labour Cost (\$\$)			6,385.00	4,055.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >