

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20013394/DVF3Q2

Date: 25/01/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713MKF

Claimant
Vehicle No : SMU4108H

Insured Vehicle No : SLM1606KK

Date of Loss: 04/12/2020

Nature of Claim: TP

Claim No: 631654

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU4108H**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A)

Engine No: 3A92UGP2610

Reg. Date: 26/03/2018 (Man. Year: 2017)

Chassis No: MMBSTA13AJH000997

Colour: Silver

Odometer: 71489 km

Engine Capacity: 1193 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55R15

Rear Tyre Size:

195/55R15

Front Left Side: Michelin 5 mm

Rear Left Side:

Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,074.30	3,303.10	8,771.20	72.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,400.00	1,790.00	3,610.00	66.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,474.30	5,093.10	12,381.20	70.85
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	17,474.30	4,000.00	13,474.30	77.11
+ GST 7.00/7.00% (S\$)	1,223.20	280.00	943.20	77.11
Nett Amount (S\$)	18,697.50	4,280.00	14,417.50	77.11

INSPECTION

Date of Assignment: 07/12/2020

Date Inspected: 07/12/2020 Inspected At:

JWG International Pte Ltd (HQ)

Blk 10, Ang Mo Kio Ind Park 2A,, #03-

08 AMK AutoPoint

Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Jan 2021)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU4108H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Bent/Dented	1,009.00 FL	*1,009.00 FL
2	1		*REAR DOOR WINDOW MOULDING LH	Not Necessary	68.00 FL	*- FL
3	1		*REAR DOOR WEATHER STRIP LH	Serviceable	168.00 FL	*- FL
4	1		*REAR DOOR INNER TRIM BOARD LH	Not Necessary	617.00 FL	*- FL
5	1		*REAR DOOR LOCK LH	Not Necessary	294.00 FL	*- FL
6	1		*REAR DOOR WINDOW MOTOR LH	Not Necessary	349.00 FL	*- FL
7	1		*REAR DOOR WINDOW REGULATOR LH	Not Necessary	318.00 FL	*- FL
8	1		*REAR DOOR BLACK PLASTIC LH	Serviceable	95.00 FL	*- FL
9	1		*REAR DOOR QUARTER GLASS MOULDING LH	Not Necessary	101.00 FL	*- FL
10	1		*REAR WINDSCREEN MOULDING	Necessary	219.00 FL	*105.00 FL
11	2		*TAIL LAMP LH	Not Necessary	476.00 FL	*- FL
12	2		*TAIL LAMP PANEL LH	Not Necessary	278.00 FL	*- FL
13	2		*TAIL LAMP LOWER BRACKET LH	Not Necessary	90.00 FL	*- FL
14	1		*REAR BUMPER	Cut/Dented	808.00 FL	*808.00 FL
15	2		*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	40.00 FL	*- FL
16	2		*REAR FENDER LH	Dented	923.00 FL	*923.00 FL
17	2		*REAR FENDER INNER SHIELD LH	Not Necessary	38.00 FL	*- FL
18	2		*REAR FENDER INNER TRIM LH	Not Necessary	368.00 FL	*- FL
19	2		*REAR WHEEL HOUSING LH	Not Necessary	887.00 FL	*- FL
20	1		*REAR WHEEL BEARING & HUB ASSY LH	Not Necessary	314.00 FL	*- FL
21	1		*REAR ABSORBER LH	Distorted	214.00 FL	*214.00 FL
22	1		*REAR AXLE	Not Necessary	1,080.00 FL	*- FL
23	1		*FUEL TANK FILLER PIPE	Not Necessary	173.00 FL	*- FL
24	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
25	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
26	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
27	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*40.00 FS
28	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
30	1		*SPORT RIM	Cut	1,500.00 FS	*450.00 FS
31	1		*TYRE	Not Necessary	300.00 FS	*- FS
32	1		*REAR DOOR EDGE PROTECTOR	Serviceable	600.00 FS	*- FS
33	1		*REAR DOOR PROTECTOR	Serviceable	300.00 FS	*- FS
34	1		*REAR BUMPER LOWER LID	Not Necessary	1,000.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,967.00	3,609.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	892.70	305.90
Total Parts (\$\$)	12,074.30	3,303.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,600.00	700.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,600.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	40.00
6	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	300.00	120.00
7	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
8	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	150.00
9	TO CONDUCT COMPUTERIZED 4 WHEEL ALIGNMENT	New	150.00	60.00
10	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
11	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (S\$)			5,400.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >