

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20013396/UPS3Q2
Date: 07/01/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100413657
Claimant Vehicle No :	SKW8906H	Insured Vehicle No :	SKT1535G
Date of Loss:	04/12/2020	Nature of Claim:	TP
		Claim No:	3850950288SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW8906H		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Engine No:	1ZRY223937
Reg. Date:	19/11/2015 (Man. Year: 2015)	Chassis No:	MR053REH104541162
Colour:	Silver	Odometer:	108606 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,650.30	2,892.65	3,757.65	56.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,000.00	2,110.00	2,890.00	57.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,650.30	5,002.65	6,647.65	57.06
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	11,650.30	4,000.00	7,650.30	65.67
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,502.00		

INSPECTION

Date of Assignment:	04/12/2020	
Date Inspected:	04/12/2020	Inspected At: Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S DOOR	Badly Dented	1,079.60 FL	*1,079.60 FL
2	1		*SET FRONT O/S DOOR FRAME STICKER	Necessary	79.20 FL	*79.20 FL
3	1		*FRONT O/S DOOR GLASS REGULATOR	Not Necessary	228.60 FL	*- FL
4	1		*FRONT O/S DOOR GLASS OUTER MOULDING	Necessary	150.30 FL	*150.30 FL
5	1		*FRONT O/S DOOR WEATHERSTRIP	Necessary	157.80 FL	*157.80 FL
6	1		*FRONT O/S DOOR INNER LOCK	Not Necessary	577.10 FL	*- FL
7	16		*FRONT O/S DOOR TRIM BOARD CLIPS	Not Necessary	76.80 FL	*- FL
8	1		*REAR O/S DOOR	Badly Dented	1,069.20 FL	*1,069.20 FL
9	1		*SET REAR O/S DOOR FRAME STICKER	Necessary	74.30 FL	*74.30 FL
10	1		*REAR O/S DOOR GLASS REGULATOR	Not Necessary	212.40 FL	*- FL
11	1		*REAR O/S DOOR GLASS OUTER MOULDING	Necessary	150.30 FL	*150.30 FL
12	2		*REAR O/S DOOR TOP & LOW HINGE	Not Necessary	159.60 FL	*- FL
13	1		*REAR O/S DOOR CHECKER	Not Necessary	146.70 FL	*- FL
14	1		*REAR O/S DOOR WEATHERSTRIP	Necessary	152.70 FL	*152.70 FL
15	16		*REAR O/S DOOR TRIM BOARD CLIPS	Not Necessary	76.80 FL	*- FL
16	1		*REAR O/S DOOR INNER LOCK	Not Necessary	542.30 FL	*- FL
17	1		*O/S ROCKER PANEL	Repair	386.70 FL	*- FL
18	1		*O/S ROCKER PANEL TUFF-KOTE STICKER	Not Necessary	159.30 FL	*- FL
19	1		*REAR O/S SPORT RIM	Cut	969.98 FS	*680.00 FS
20	1		*REAR BUMPER	Repair	482.80 FL	*- FL
21	1		*REAR BUMPER O/S SIDE RETAINER	Not Necessary	104.40 FL	*- FL
22	1		*REAR BUMPER O/S SIDE BRACKET CLIPS	Not Necessary	6.90 FL	*- FL
23	8		*REAR BUMPER CLIPS	Necessary	36.80 FL	*36.80 FL
24	1		*REAR O/S FENDER	Repair	928.90 FL	*- FL
25	6		*REAR O/S FENDER INNER GARNISH CLIPS	Not Necessary	27.60 FL	*- FL
26	1		*REAR O/S WHEEL TYRE	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,417.08	3,630.20
- List Item Discount on L Items 25.00/25.00% (\$)	1,766.78	737.55
Total Parts (\$)	6,650.30	2,892.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No Particulars		Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK & ADJUST WHEEL BALANCING & WHEEL ALIGNMENT	New	150.00	60.00
2	TO TRANSFER FRONT & REAR O/S DOOR TRIM BOARD ,GARNISH ,GLASS ,CHANNEL ,REGULATOR ,MOTOR ,HINGE ,MOULDING ,INNER LOCK,HANDLE,WEATHERSTRIP & NECESSARY PARTS INTO NEW DOOR	New	300.00	120.00
3	TO REMOVE & REFIX CARPET ,FLOOR MAT ,GARNISH ,CUSHION & NECESSARY PARTS ,TO ENABLE REPAIR O/S ROCKER PANEL ,REAR O/S FENDER & O/S CENTRE DOOR PILLAR PANEL	New	120.00	0.00
4	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM ,INCLUDING DOOR CENTRE LOCKING SYSTEM	New	60.00	30.00
5	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK ,STRAIGHTEN & KNOCKING OUT REAR O/S FENDER ,O/S ROCKER PANEL ,O/S CENTRE DOOR PILLAR PANEL,& NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	1,900.00	600.00
6	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	2,200.00	1,200.00
7	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	150.00	60.00
8	TO DIAGNOSE & RE-SET REAR O/S WHEEL SPEED (ABS) SENSOR & AIR-BAG SENSOR	New	120.00	40.00
Gross Labour Cost (\$)			5,000.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >