



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3007X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	458.60	-
1	REAR BUMPER UNDER COVER	DEFORMED	552.60	552.60
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	232.00	-
10	BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SIDE RETAINER LH / RH	NOT NECESSARY	112.70	-
1	TOWING COVER	NOT NECESSARY	82.70	-
	LESS 25% DISCOUNT		-365.15	-143.65
			1,095.45	430.95
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	NOT WORKING	135.70	135.70
1	REAR BUMPER MAT (SN)	NOT NECESSARY	50.00	-
			185.70	135.70
	<u>LABOUR</u>			
	PANEL BEATING.		600.00	320.00
	SPRAY PAINTING.		500.00	200.00
	WIRING.	NOT NECESSARY	60.00	-
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE / REFIX REVERSE SENSOR.		60.00	30.00
			1,280.00	550.00
	GRAND TOTAL		2,561.15	1,116.65
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			900.00

Report Ref No. NS/INC20013398/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.