Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20013422/R1PA3Q2

Date: 10/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900097230

Claimant Vehicle No: Insured Vehicle No: SLC3299C

Date of Loss: 03/12/2020 Nature of Claim: TP Claim No: 7688573638SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKZ6959C

 Make & Model:
 BMW 320I, 2.0 (A)
 Engine No:
 H0063503B48B20A

 Reg. Date:
 21/01/2020 (Man. Year: 2019)
 Chassis No:
 WBA5F32020FH79658

Colour: Blue Odometer: 12115 km

Engine Capacity: 1998 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm
Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		10,226.60	7,339.60	2,887.00	28.23
Miscellaneous Items		0.00	0.00	0.00	
Labour		5,039.00	3,910.00	1,129.00	22.41
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	15,265.60	11,249.60	4,016.00	26.31
	+ GST 7.00/7.00% (S\$)	1,068.59	787.47	281.12	26.31
	Nett Amount (S\$)	16,334.19	12,037.07	4,297.12	26.31

+ Car Rental (4.0 x S\$120.00/day + 7.00% GST) (S\$) 513.60 + Doc/Search Fee (S\$) 2.00

Nett Liability (S\$) 12,552.67

INSPECTION

Date of Assignment: 21/12/2020

Date Inspected: 21/12/2020 Inspected At: Performance Motors Limited (HQ)

303 Alexandra Road, Singapore

Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL Manager: CHEW HSIAO TONG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*TRUNK LID	Bent	1,315.60 FS	*1,322.15 FS
3	1		*REAR BUMPER CARRIER	Serviceable	479.65 FS	*- FS
4	1		*REAR BUMPER LH SIDE GUIDE	Serviceable	58.25 FS	*-FS
5	1		*REAR BUMPER RH SIDE GUIDE	Serviceable	58.25 FS	*-FS
6	1		*REAR BUMPER TRIM PANEL BOTTOM (MSP)	Serviceable	217.90 FS	*-FS
7	1		*REAR BUMPER MOUNTING (MSP)	Serviceable	142.65 FS	*-FS
8	1		*REAR BUMPER LH MOUNTING CORNER (MSP)	Serviceable	161.40 FS	*-FS
9	1		*REAR BUMPER RH MOUNTING CORNER (MSP)	Serviceable	161.40 FS	*- FS
10	1		*REAR BUMPER TRIM PANEL (MSP/PMA PDC)	Repair	1,593.65 FS	*-FS
11	1		*PLAQUE 74MM	Necessary	71.95 FS	*71.95 FS
12	2		*GROMMET	Necessary	1.60 FS	*1.60 FS
13	1		*M PERFORMANCE RR DIFFUSER CARBON	Cracked	3,279.40 FS	*3,279.40 FS
14	1		*M PERFORMANCE REAR SPOILER CARBON	Necessary	1,400.10 FS	*1,400.10 FS
15	4		*DECOUPLING RING	Not Necessary	20.40 FS	*-FS
16	2		*EXPANDING NUT	Necessary	5.70 FS	*5.70 FS
17	1		*M PERFORMANCE RR BUMPER TRIM BLACK	Scratched	1,006.20 FS	*1,006.20 FS
18	1		*(DG/SL) ADHESIVE SET 1K 80ML	Necessary	102.50 FS	*102.50 FS
F=Franchise part. S=SpcNett.						
				Total Parts (S\$)	10,226.60	7,339.60

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	TO REPLACE REAR BUMPER PANEL AND ATTACHMENTS ,BOOTLID ,SPOILER	New	2,550.00	1,700.00					
2	TO RESPRAY REAR BUMPER AND BOOTLID	New	1,923.00	1,730.00					
3	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIR	New	271.00	230.00					
4	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00					
5	TO CARRY OUT BODY CAVITYPRESER VATION (PER PANEL)	New	118.00	100.00					
	Gross Labour Cost (S\$)		5,039.00	3,910.00					

< END OF ESTIMATES >

Report was unsubmitted during this print-out.