

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013427/EQF3E2

Date: 19/05/2021

REFERENCE

Insured/Claimant:	TAN JUN HUA	Policy No:	2070112057		
Date of Loss:	04/12/2020	Nature of Claim:	OD	Claim No:	1374156517SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU1686A	Engine No:	G3LCKP165735
Make & Model:	KIA STONIC, 998cc (A)	Chassis No:	KNAD6811VL6382828
Reg. Date:	28/07/2020 (Man. Year: 2019)	Odometer:	5405 km
Colour:	Silver		
Engine Capacity:	998 cc		
Market Value/New Car Price:	S\$76,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,898.00	8,834.40	2,063.60	18.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,620.00	3,670.00	950.00	20.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,518.00	12,504.40	3,013.60	19.42
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	15,218.00	12,204.40	3,013.60	19.80
+ GST 7.00/7.00% (S\$)	1,065.26	854.31	210.95	19.80
Nett Amount (S\$)	16,283.26	13,058.71	3,224.55	19.80

INSPECTION

Date of Assignment:	07/12/2020	
Date Inspected:	07/12/2020 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	8.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
2	1		*COVER-FR BUMPER UPR	Broken	476.00 FL	*476.00 FL
3	1		*CAP-FRONT HOOK	Missing	5.00 FL	*5.00 FL
4	1		*SKID PLATE-FR BUMPER	Crushed	55.00 FL	*55.00 FL
5	1		*LIP ASSY-FRONT BUMPER	Not Necessary	32.00 FL	*- FL
6	1		*GRILLE ASSY-RADIATOR	Broken	324.00 FL	*324.00 FL
7	1		*COVER-RADIATOR GRILLE UPR	Broken	46.00 FL	*46.00 FL
8	1		*MOULDING-FRONT BUMPER A/INTAKE	Broken	61.00 FL	*61.00 FL
9	1		*STRIP-FR BUMPER	Necessary	27.00 FL	*27.00 FL
10	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	98.00 FL	*98.00 FL
11	1		*STIFFENER-FR BPR LWR	Broken	123.00 FL	*123.00 FL
12	1		*AIR DUCT-FR BUMPER, RH	Not Necessary	38.00 FL	*- FL
13	1		*COVER-FR BUMPER FOG LAMP, RH	Cut	64.00 FL	*64.00 FL
14	1		*BRACKET-FR BUMPER SIDE, LH	Broken	13.00 FL	*13.00 FL
15	1		*BRACKET-FR BUMPER SIDE, RH	Broken	13.00 FL	*13.00 FL
16	1		*COVER-FR BUMPER, LWR	Broken	367.00 FL	*367.00 FL
17	1		*GRILLE-FRONT BUMPER	Broken	96.00 FL	*96.00 FL
18	1		*PANEL ASSY-HOOD	Dented	904.00 FL	*904.00 FL
19	1		*HINGE ASSY-HOOD, LH	Bent	43.00 FL	*43.00 FL
20	1		*HINGE ASSY-HOOD, RH	Bent	43.00 FL	*43.00 FL
21	1		*LATCH ASSY-HOOD	Bent	101.00 FL	*101.00 FL
22	1		*PAD-HOOD INSULATING	Crushed	119.00 FL	*119.00 FL
23	1		*PANEL-FENDER, RH	Dented	401.00 FL	*401.00 FL
24	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
25	1		*COVER ASSY-COWL TOP, RH	Cut	10.00 FL	*10.00 FL
26	1		*LAMP ASSY-HEAD, LH	Not Necessary	1,845.00 FL	*- FL
27	1		*LAMP ASSY-HEAD, RH	Broken	1,845.00 FL	*1,845.00 FL
28	1		*CARRIER ASSY-FRONT END MODULE	Dented	556.00 FL	*556.00 FL
29	1		*BEAM COMPLETE-FR BUMPER	Dented	544.00 FL	*544.00 FL
30	1		*GUARD- AIR, RH	Broken	14.00 FL	*14.00 FL
31	1		*CONDENSER ASSY-COOLER	Dented	648.00 FL	*648.00 FL
32	1		*GUARD-AIR RADIATOR, UPR	Broken	23.00 FL	*23.00 FL
33	1		*RADIATOR ASSY	Dented	584.00 FL	*584.00 FL
34	1		*BLOWER ASSY	Broken	536.00 FL	*536.00 FL
35	1		*RESERVOIR & PUMP ASSY-WASHER	Not Necessary	152.00 FL	*- FL
36	1		*MANIFOLD ASSY-INTAKE	Not Necessary	500.00 FL	*- FL
37	1		*COOLANT (4L)	Necessary	26.00 FL	*26.00 FL
38	1		*HOSE-RADIATOR LOWER (Supplementary)	Torn	86.00 FL	*86.00 FL
39	1		*AIR GUIDE-INTERCOOLER (Supplementary)	Broken	32.00 FL	*32.00 FL
40	1		*DUCT ASSY-AIR (Supplementary)	Broken	97.00 FL	*97.00 FL
41	1		*HORN ASSY-LOW PITCH (Supplementary)	Broken	64.00 FL	*64.00 FL
42	1		*FITTING-COOLANT INLET (Supplementary)	Broken	34.00 FL	*34.00 FL
43	1		*HOSE ASSY-WATER (Supplementary)	Torn	78.00 FL	*78.00 FL
44	1		*TUBE-RETURN (Supplementary)	Bent	36.00 FL	*36.00 FL
45	1		*SENSOR ASSY-KNOCK (Supplementary)	Broken	61.00 FL	*61.00 FL
46	1		*BODY ASSY-THROTTLE (Supplementary)	Broken	526.00 FL	*526.00 FL
47	1		*GENERATOR ASSY (Supplementary)	Broken	1,110.00 FL	*1,110.00 FL
48	1		*COVER ASSY-COWL TOP (Supplementary)	Cut	166.00 FL	*166.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*SENSOR-EXTERNAL AMBIENT (Supplementary)	Broken	47.00 FL	*47.00 FL
50	1		*WIRING ASSY-BATTERY (Supplementary)	Broken	484.00 FL	*484.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,615.00	11,038.00
- List Item Discount on L Items 20.00/20.00% (S\$)	2,717.00	2,203.60
Total Parts (S\$)	10,898.00	8,834.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, BONNET, FRT SUPPORT & RHF FENDER. REPAIR LHF FENDER	New	2,400.00	2,000.00
2	RESPRAY FRT BUMPER, BONNET, LHF FENDER & RHF FENDER	New	1,400.00	1,050.00
3	TO RENEW AC CONDENSER & RADIATOR	New	100.00	100.00
4	TOP UP AIRCON GAS	New	80.00	80.00
5	TO RENEW FRT INTAKE MANIFOLD	New	200.00	0.00
6	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	40.00
9	SUPPLY FRT NUMBER PLATE WITH CASING	New	50.00	50.00
10	REMOVE & REPLACE ALTERNATOR, THROTTLE BODY & WATER PIPE (Supplementary)	New	200.00	200.00
Gross Labour Cost (\$)			4,620.00	3,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >