



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Mr Tan Jun Hua Reg No/Reg Date SMU1686A / 28/07/202 Date In/Mileage / 5405 Chassis No KNAD6811VL6382828 Engine No G3LCKP165735 Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	05/12/2020/ 12:35	QUE	261 / Edwin Caina	25328

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, BONNET, FRT SUPPORT & RH FENDER 449 X 6 REPAIR LHF FENDER				2400.00
E PNT98000 RESpray FRT BUMPER, BONNET, LHF FEDNDER & RH FENDER 859				1400.00
E PNT88000 TO RENEW AC CONDENSER & RADIATOR				100.00
M SUNDRY TOP UP AIRCON GAS				80.00
A 11900199 TO RENEW FRT INTAKE MANIFOLD				200.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				40.00
M SUNDRY SUPPLY FRT NUMBER PLATE WITH CASING				50.00
M SUNDRY Sundries				30.00
M COVER-FR BUMPER UPR	1.00	476.00	20.00	380.80
M CAP-FRONT HOOK	1.00	5.00	20.00	4.00
M SKID PLATE-FR BUMPER	1.00	55.00	20.00	44.00
M LIP ASSY-FRONT BUMPER	1.00	32.00	20.00	25.60
M GRILLE ASSY-RADIATOR	1.00	324.00	20.00	259.20
M COVER-RADIATOR GRILLE UPR	1.00	46.00	20.00	36.80
M MOULDING-FRONT BUMPER A/INTAKE	1.00	61.00	20.00	48.80
M STRIP-FR BUMPER	1.00	27.00	20.00	21.60
M ABSORBER-FRONT BUMPER ENERGY	1.00	98.00	20.00	78.40
M STIFFNER-FR BPR LWR	1.00	123.00	20.00	98.40
M AIR DUCT-FR BUMPER,RH	1.00	38.00	20.00	30.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Mr Tan Jun Hua Reg No/Reg Date SMU1686A / 28/07/202 Date In/Mileage / 5405 Chassis No KNAD6811VL6382828 Engine No G3LCKP165735 Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	05/12/2020/ 12:35	QUE	261 / Edwin Caina	25328			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M COVER-FR BUMPER FOG LAMP,RH					1.00	64.00	20.00	51.20
M BRACKET-FR BUMPER SIDE,LH					1.00	13.00	20.00	10.40
M BRACKET-FR BUMPER SIDE,RH					1.00	13.00	20.00	10.40
M COVER-FR BUMPER,LWR					1.00	367.00	20.00	293.60
M GRILLE-FRONT BUMPER					1.00	96.00	20.00	76.80
M PANEL ASSY-HOOD					1.00	904.00	20.00	723.20
M HINGE ASSY-HOOD,LH					1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD,RH					1.00	43.00	20.00	34.40
M LATCH ASSY-HOOD					1.00	101.00	20.00	80.80
M PAD-HOOD INSULATING					1.00	119.00	20.00	95.20
M PANEL-FENDER,RH					1.00	401.00	20.00	320.80
M ORNAMENT-KIA NO.115					1.00	32.00	20.00	25.60
M COVER ASSY-COWL TOP,RH					1.00	10.00	20.00	8.00
M LAMP ASSY-HEAD,LH					1.00	1845.00	20.00	1476.00
M LAMP ASSY-HEAD,RH					1.00	1845.00	20.00	1476.00
M CARRIER ASSY-FRONT END MODULE					1.00	556.00	20.00	444.80
M BEAM COMPLETE-FR BUMPER					1.00	544.00	20.00	435.20
M GUARD-AIR,RH					1.00	14.00	20.00	11.20
M CONDENSER ASSY-COOLER					1.00	648.00	20.00	518.40
M GUARD-AIR RADIATOR,UPR					1.00	23.00	20.00	18.40
M RADIATOR ASSY					1.00	584.00	20.00	467.20
M BLOWER ASSY					1.00	536.00	20.00	428.80
M RESERVOIR & PUMP ASSY-WASHER					1.00	152.00	20.00	121.60
M MANIFOLD ASSY-INTAKE					1.00	500.00	20.00	400.00
M COOLANT (4L)					1.00	26.00	23.00	20.02

SURVEYOR NAME: Steve CLKKSURVEYOR SIGNATURE: DD- NM ALDATE: EXCL - ?REMARKS: P/P**Confirm & accepted by**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized Signatory and Company Stamp

No illegal modification is allowed

Valued at 13,060.42 Net 7% GST on 13060.42 Total Payable 13,974.65

Valid for 30 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.