

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20013430/UTD3Q2

Date: 30/12/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29144669ATM

Claimant
Vehicle No : SKB9733T

Insured Vehicle No : SMA3769L

Date of Loss: 03/12/2020

Nature of Claim: TP

Claim No: 631651

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKB9733T**

Make & Model: PEUGEOT 308, 1.6 TURBO SR (A)

Engine No: 10FJBJ1002591

Reg. Date: 14/07/2011 (Man. Year: 2010)

Chassis No: VF34C5FVAAS285197

Colour: White

Odometer: 114584 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17

Rear Tyre Size:

225/45R17

Front Left Side: Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,738.69	3,643.24	10,095.45	73.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,250.00	3,300.00	2,950.00	47.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,988.69	6,943.24	13,045.45	65.26
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	19,988.69	4,200.00	15,788.69	78.99

INSPECTION

Date of Assignment: 07/12/2020

Date Inspected: 07/12/2020 Inspected At:

Euro Success Services Pte Ltd (HQ)

1 KAKI BUKIT AVENUE 6 #02-03

AUTOBAY

Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2020)
Parts:	144	PEUGEOT 308 1.6 TURBO SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB9733T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Badly Dented	650.50 FL	*650.50 FL
2	1		*REAR BOOT LOGO	Not Necessary	38.60 FL	*- FL
3	1		*REAR BOOT EMBLEM PEUGEOT	Necessary	30.94 FL	*30.94 FL
4	1		*REAR BOOT EMBLEM 308	Necessary	38.60 FL	*38.60 FL
5	1		*REAR BOOT OUTER GARNISH	Not Necessary	123.55 FL	*- FL
6	2		*REAR BOOT LICENSE LAMPS	Not Necessary	84.40 FL	*- FL
7	1		*REAR BOOT INNER LOCK	Not Necessary	115.50 FL	*- FL
8	1		*REAR BOOT LOCK STRIKER	Not Necessary	76.15 FL	*- FL
9	2		*REAR BOOT HINGES L-R	Not Necessary	179.00 FL	*- FL
10	1		*REAR BOOT W/STRIP	Twisted	89.95 FL	*85.00 FL
11	1		*REAR BUMPER	Distorted	480.95 FL	*450.00 FL
12	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	97.10 FL	*- FL
13	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
14	1		*REAR END PANEL	Badly Dented	791.70 FL	*688.00 FL
15	1		*REAR END PANEL GARNISH	Distorted	82.90 FL	*82.90 FL
16	1		*REAR SPARE TYRE FLOOR PANEL	Repair	450.00 FL	*- FL
17	1		*REAR EXHAUST MUFFLER	Repair	550.00 FL	*- FL
18	1		*EXHAUST SILENCER CENTRE	Repair	596.20 FL	*- FL
19	2		*REAR EXHAUST MOUNTINGS	Not Necessary	57.20 FL	*- FL
20	2		*REAR FENDER L-R	Repair	1,669.60 FL	*- FL
21	2		*REAR FENDER INNER TRIMS L-R	Not Necessary	560.90 FL	*- FL
22	10		*REAR FENDER INNER TRIMS CLIPS	Not Necessary	45.00 FL	*- FL
23	2		*REAR FENDER INNER SHIELDS L-R	Not Necessary	163.00 FL	*- FL
24	1		*REAR TAILLAMPS L-R	N/s Cracked	721.90 FL	*290.00 FL
25	2		*REAR TAILLAMP PANELS L-R	Repair	310.00 FL	*- FL
26	1		*REAR WIND SCREEN MOULDING	Not Necessary	120.65 FL	*- FL
27	1		*FRONT BONNET	Repair	641.50 FL	*- FL
28	1		*FRONT BONNET SEAL	Not Necessary	48.20 FL	*- FL
29	1		*FRONT BONNET INSULATOR	Not Necessary	121.81 FL	*- FL
30	10		*FRONT BONNET INSULATOR CLIPS	Not Necessary	55.00 FL	*- FL
31	2		*FRONT BONNET HINGES	Not Necessary	91.00 FL	*- FL
32	1		*FRONT BONNET LOCK	Not Necessary	106.50 FL	*- FL
33	1		*FRONT BONNET LOCK CABLE	Not Necessary	89.90 FL	*- FL
34	1		*FRONT BUMPER	Distorted	480.95 FL	*450.00 FL
35	1		*FRONT BUMPER CENTRE GRILLE	Torn	68.85 FL	*68.85 FL
36	2		*FRONT BUMPER SIDE GRILLE L-R	Not Necessary	84.40 FL	*- FL
37	1		*FRONT BUMPER REINFORCEMENT	Distorted	311.40 FL	*311.40 FL
38	2		*FRONT BUMPER REINFORCEMENT STAYS	Not Necessary	230.00 FL	*- FL
39	2		*FRONT BUMPER SIDE RETAINERS L-R	Not Necessary	83.00 FL	*- FL
40	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
41	1		*FRONT GRILLE ASSY	Distorted	280.30 FL	*215.00 FL
42	1		*FRONT GRILLE LOGO	Not Necessary	68.50 FL	*- FL
43	2		*FRONT HEAD LAMPS L-R	Holder Cracked	721.00 FL	*721.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	2		*FRONT HEAD LAMPS SIDE GARNISH L-R	Not Necessary	97.20 FL	*- FL
45	1		*FRONT SUPPORT PANEL ASSY	Repair	581.75 FL	*- FL
46	1		*AIR CON CONDENSER	Not Necessary	962.83 FL	*- FL
47	1		*AIR CON DISCHARGE PIPE	Not Necessary	381.62 FL	*- FL
48	1		*AIR CON SUCTION PIPE	Not Necessary	365.20 FL	*- FL
49	1		*AIR CLEANER INTAKE PIPE	Not Necessary	89.60 FL	*- FL
50	1		*AIR CLEANER BOX ASSY	Not Necessary	281.62 FL	*- FL
51	1		*RADIATOR ASSY	Not Necessary	1,101.60 FL	*- FL
52	1		*AIR CON FAN COWING	Cracked	219.24 FL	*180.00 FL
53	1		*AIR CON FAN BLADE	Broken	78.80 FL	*78.80 FL
54	1		*RADIATOR FAN MOTOR	Not Necessary	481.60 FL	*- FL
55	1		*SAFETY BELTS	Not Necessary	580.60 FL	*- FL
56	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
57	1		*REAR NO PLATE	Distorted	60.00 FS	*40.00 FS
58	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
59	1		*REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
60	1		*FRONT NO PLATE	Distorted	60.00 FS	*40.00 FS
61	1		*AIR CON OIL	Not Necessary	60.00 FS	*- FS
62	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,968.26	4,750.99
- List Item Discount on L Items 25.00/25.00% (\$)	4,229.57	1,107.75
Total Parts (\$)	13,738.69	3,643.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REFIX REVERSE SENSOR AND CAMERA	New	200.00	50.00
2	TO RESPRAY UNDERCOATING	New	300.00	60.00
3	TO REMOVE,REFIX REAR EXHAUST SYSTEM	New	200.00	60.00
4	TO CHECK FRONT AND REAR ELECTRICAL WIRING	New	150.00	30.00
5	TO RESPRAY PAINTING AND ETC	New	2,400.00	1,600.00
6	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS	New	3,000.00	1,500.00
Gross Labour Cost (\$\$)			6,250.00	3,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >