

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120**Our File No:** CS/AIG20013431/EVF3Q2**Date:** 15/01/2021REFERENCE

Insured/Claimant:	WEE SIEW KHENG	Policy No:	1900255511
Date of Loss:	04/12/2020	Nature of Claim:	OD
		Claim No:	0292046391SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ9160T	Engine No:	3A92UJC3543
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AKH003639
Reg. Date:	10/12/2019 (Man. Year: 2019)	Odometer:	9800 km
Colour:	Grey		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$59,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,325.82	4,072.29	1,253.53	23.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,605.00	5,965.00	1,640.00	21.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,930.82	10,037.29	2,893.53	22.38
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	12,330.82	9,437.29	2,893.53	23.47
+ GST 7.00/7.00% (S\$)	863.16	660.61	202.55	23.47
Nett Amount (S\$)	13,193.98	10,097.90	3,096.08	23.47

INSPECTION

Date of Assignment: 07/12/2020

Date Inspected: 07/12/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ,QTR ,OTR RH	Dented	763.00 FL	*763.00 FL
2	1		*PANEL ,RR COMB LAMP HSG ,RH	Bent	60.00 FL	*60.00 FL
3	1		*EXTN ,QTR PANEL ,UPR OTR RH	Not Necessary	118.00 FL	*- FL
4	1		*LAMP ASSY ,COMB ,RR RH	Broken	335.00 FL	*335.00 FL
5	2		*GROMMET ,TAIL LAMP	Necessary	6.00 FL	*6.00 FL
6	2		*GROMMET ,TAIL LAMP	Necessary	6.00 FL	*6.00 FL
7	1		*PANEL ,TRUNK LID	Dented	791.00 FL	*791.00 FL
8	1		*HINGE ,TRUNK LID ,LH	Not Necessary	203.00 FL	*- FL
9	1		*HINGE ,TRUNK LID ,RH	Not Necessary	203.00 FL	*- FL
10	1		*WEATHERSTRIP ,TRUNK LID	Crushed	157.00 FL	*157.00 FL
11	1		*LATCH ,TRUNK LID	Not Necessary	218.00 FL	*- FL
12	1		*STRIKER ,TRUNK LID LATCH	Not Necessary	20.00 FL	*- FL
13	1		*MARK ,ATTRAGE	Necessary	21.00 FL	*21.00 FL
14	1		*MARK,THREE-DIA	Necessary	69.00 FL	*69.00 FL
15	1		*GARNISH ,RR END PANEL	Not Necessary	336.00 FL	*- FL
16	1		*PANEL,RR END	Repair	425.00 FL	*- FL
17	1		*TRIM ,RR END	Not Necessary	66.00 FL	*- FL
18	1		*BRACKET ,RR BUMPER ,LH	Broken	28.00 FL	*28.00 FL
19	1		*BRACKET ,RR BUMPER ,RH	Broken	28.00 FL	*28.00 FL
20	8		*CLIP ,RR BUMPER	Necessary	32.00 FL	*32.00 FL
21	1		*FACE ,RR BUMPER	Dented	748.00 FL	*748.00 FL
22	2		*STOPPER ,WINDSHIELD GLASS	Necessary	6.00 FL	*6.00 FL
23	3		*SPACER ,RR WINDOW	Necessary	27.00 FL	*27.00 FL
24	1		*BODY KIT ATTRAGE	Broken	1,643.00 FS	*1,643.00 FS
25	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
26	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,399.00	4,780.00
- List Item Discount on L Items 23.00/23.00% (S\$)	1,073.18	707.71
Total Parts (S\$)	5,325.82	4,072.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON REAR BOOT LID,REAR BUMPER ,REAR BODY KIT ,CUT/WELD RH REAR FENDER ,REAR END PANEL	New	3,150.00	2,250.00
2	REMOVE AND INSTALL REAR WINDSCREEN GLASS	New	240.00	240.00
3	SUPPLY REAR WINDSCREEN SEALANT	New	80.00	80.00
4	REMOVE AND INSTALL REAR CABIN AND OTHERS ATTACHMENT TO FACILITATEREPAIR WORK	New	120.00	120.00
5	REMOVE AND INSTALL PARKING SENSOR	New	60.00	60.00
6	PAINT WORK SPRAY REAR END PANEL ,REAR BUMPER ,REAR BODY KIT,REAR BOOT LID ,RH REAR FENDER ,LH REAR FENDER AND AFFECTED PORTION	New	2,450.00	1,750.00
7	APPLICATION LAT FOR BREAK SEAL AND RESEAL REAR OPC NUMBER PLATE	New	80.00	80.00
8	SUPPLY REAR NUMBER PLATE WITH FRAME	New	50.00	50.00
9	APPLY BODY SEALANT	New	120.00	80.00
10	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
11	PERFORM RUST PREVENTION	New	80.00	80.00
12	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
13	REPAIR REAR END PANEL,REAR COMPARTMENT,TAIL LAMP HOUSING (SUPPLEMENTARY)	New	675.00	675.00
14	RESPRAY ON TAIL LAMP HOUSING AND REAR COMPARTMENT (SUPPLEMENTARY)	New	350.00	350.00
Gross Labour Cost (\$\$)			7,605.00	5,965.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >