

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013436/EQD3Q2

Date: 15/03/2021

REFERENCE

Insured/Claimant: FONG KOK XIANG, RAYMOND (HONG GUOXIANG)

Policy No: 1900110161

Date of Loss: 02/12/2020

Nature of Claim: OD Claim No: 8290212034SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM1465M	Engine No:	G3LCKP059588
Make & Model:	KIA STONIC, 998cc (A)	Chassis No:	KNAD6811VL6315057
Reg. Date:	19/06/2019 (Man. Year: 2019)	Odometer:	22667 km
Colour:	White		
Engine Capacity:	998 cc		
Market Value/New Car Price:	S\$77,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R17	Rear Tyre Size:	205/55R17
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,669.20	815.20	1,854.00	69.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	700.00	2,150.00	75.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,519.20	1,515.20	4,004.00	72.55
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	5,219.20	1,215.20	4,004.00	76.72
+ GST 7.00/7.00% (S\$)	365.34	85.06	280.28	76.72
Nett Amount (S\$)	5,584.54	1,300.26	4,284.28	76.72

INSPECTION

Date of Assignment: 07/12/2020

Date Inspected: 16/12/2020 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-FR BUMPER UPR	Broken	476.00 FL	*476.00 FL
2	1		*COVER-FR BUMPER LWR	Broken	367.00 FL	*367.00 FL
3	1		*SKID PLATE-FR BUMPER	Broken	55.00 FL	*55.00 FL
4	1		*LIP ASSY-FRONT BUMPER	Not Necessary	32.00 FL	*- FL
5	1		*GRILLE-FRONT BUMPER	Broken	96.00 FL	*96.00 FL
6	1		*GRILLE ASSY-RADIATOR	Not Necessary	324.00 FL	*- FL
7	1		*STRIP-FR BUMPER	Not Necessary	27.00 FL	*- FL
8	1		*BRACKET-FR BUMPER SIDE,LH	Not Necessary	13.00 FL	*- FL
9	1		*COVER-FR BUMPER FOG LAMP,LH	Not Necessary	64.00 FL	*- FL
10	1		*LAMP ASSY-HEAD,LH	Not Necessary	1,845.00 FL	*- FL
11	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
					Sub Total (\$\$)	3,329.00 1,014.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	659.80 198.80
					Total Parts (\$\$)	2,669.20 815.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW FRT BUMPER.REPAIR BONNET & LHF FENDER	New	1,600.00	200.00
2	RESPRAY FRT BUMPER,BONNET & LHF FENDER	New	1,050.00	350.00
3	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
5	SUPPLY FRT NUMBER PLATE WITH CASING	New	50.00	0.00
Gross Labour Cost (\$\$)			2,850.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >