



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 6467H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BOOTLID	DENTED / BENT	1,122.50	1,122.50
1	BOOT LID LOGO	NECESSARY	120.00	61.60
1	BOOT LID EMBLEM 'CAMRY'	NOT NECESSARY	90.00	-
1	BOOT LID EMBLEM 'HYBRID'	NECESSARY	80.00	68.00
1	BOOTLID EMBLEM '2.5G'	NECESSARY	80.00	60.50
1	BOOTLID LOCK	SERVICEABLE	320.00	-
1	BOOT LID DETECTOR	CRACKED	250.00	195.20
1	BOOT LID WEATHERSTRIP	NOT NECESSARY	266.30	-
1	REAR BUMPER	DENTED / DEFORMED	890.00	657.60
2	REAR BUMPER SIDE RETAINER @\$62.40	NOT NECESSARY	124.80	-
1	REAR BUMPER REINFORCEMENT	DENTED	455.80	399.50
1	REAR BUMPER LOWER SPOILER	DEFORMED / TORN	580.30	393.00
4	REAR BUMPER REVERSE SENSOR @\$280.60	O/S SHORTED (1PC ONLY)	1,122.40	280.60
1	REAR END PANEL	TO REPAIR SEE LABOUR	677.50	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	422.50	-
	LESS 25% DISCOUNT		-1,650.53	-809.63
			4,951.57	2,428.87
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	200.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	120.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-
			360.00	20.00
<b><u>LABOUR</u></b>				
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,000.00	600.00
	TO SPRAY PAINT AFFECTED AREA.		1,000.00	750.00
	TUFF COAT.		250.00	30.00

Report Ref No. CS/SMO20013444/Uqd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING CHECK.		80.00	20.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		120.00	50.00
	TRANSFER BOOTLID MECHANISM.		80.00	60.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.		240.00	40.00
			2,770.00	1,550.00
	<b>GRAND TOTAL</b>		<b>8,081.57</b>	<b>3,998.87</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,200.00</b>

Report Ref No. CS/SMO20013444/Uqd3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.