

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013447/T1GS3Q2

Date: 02/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070159022
Claimant
Vehicle No : SHA3434L **Insured Vehicle No :** GBJ183D
Date of Loss: 05/12/2020 **Nature of Claim:** TP **Claim No:** 6752158969SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA3434L**
 Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZR2G76775
 Reg. Date: 15/04/2020 (Man. Year: 2020) Chassis No: JTDKB3FUX03091260
 Colour: Blue Odometer: 60103 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
 Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,378.37	773.85	1,604.52	67.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	780.00	220.00	22.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,378.37	1,553.85	1,824.52	54.01
+ GST 7.00/7.00% (S\$)	236.49	108.77	127.72	54.01
Nett Amount (S\$)	3,614.86	1,662.62	1,952.24	54.01
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 07/12/2020
 Date Inspected: 07/12/2020 Inspected At: ComfortDelGro Engineering Pte Ltd
 (Loyang)
 59 Loyang Drive
 Singapore 508969
 Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL -FENDER RH	Bent	945.30 FL	*945.30 FL
2	1		*LAMP ASSY -HEAD	Not Necessary	1,993.65 FN	*- FN
3	1		*EMBLEM -BLUE DRIVE	Necessary	86.50 FL	*86.50 FL
4	1		*BRACKET -FR BUMPER	Not Necessary	12.00 FN	*- FN

F=Franchise part. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	3,037.45	1,031.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	257.95	257.95
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	401.13	0.00
Total Parts (\$\$)	2,378.37	773.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	320.00
2	SPRAYPAINT CHARGE	New	500.00	400.00
3	CHECK ALL LIGHTING	New	50.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	50.00	30.00
Gross Labour Cost (\$\$)			1,000.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >