

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20013449/UVD3Q2

Date: 30/12/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00111352000
Claimant Vehicle No :	SGV4701K	Insured Vehicle No :	YP9772R
Date of Loss:	05/12/2020	Nature of Claim:	TP
		Claim No:	SNM20D204690/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV4701K	Engine No:	1NZX571646
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY9305010194
Reg. Date:	15/06/2007 (Man. Year: 2007)	Odometer:	447697 km
Colour:	White		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Goodride 6 mm	Rear Left Side:	Goodride 6 mm
Front Right Side:	Goodride 6 mm	Rear Right Side:	Goodride 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,988.95	2,748.57	5,240.38	65.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	1,280.00	2,520.00	66.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,788.95	4,028.57	7,760.38	65.83
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	11,788.95	3,200.00	8,588.95	72.86

INSPECTION

Date of Assignment:	07/12/2020	
Date Inspected:	07/12/2020 Inspected At:	15 KAKI BUKIT ROAD 4 # 01-53 REPAIRER: ZOOM AUTOWERKS PTE LTD
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2020)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGV4701K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	795.60 FL	*481.20 FL
2	1		*FRONT BUMPER SIDE GARNISH O/S	Not Necessary	175.50 FL	*- FL
3	1		*FRONT BUMPER FOG LAMP O/S	Cracked	296.40 FL	*296.40 FL
4	2		*FRONT BUMPER BRACKET	Not Necessary	136.00 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER	O/s Cracked	157.20 FL	*56.20 FL
6	1		*FRONT BUMPER CENTRE BRACKET	No such part	245.60 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Dented	382.70 FL	*312.20 FL
8	1		*FRONT BUMPER CENTRE AIR-GRILLE	Torn	245.20 FL	*133.80 FL
9	1		*FRONT BUMPER RAD GRILLE	Cracked	395.60 FL	*285.10 FL
10	1		*FRONT BUMPER LOWER COVER	Not Necessary	69.50 FL	*- FL
11	1		*FRONT GRILLE LOGO	Necessary	98.00 FL	*68.10 FL
12	1		*FRONT HEADLAMP O/S	Cracked	688.70 FL	*588.20 FL
13	1		*FRONT HEADLAMP BRACKET O/S	Not Necessary	75.40 FL	*- FL
14	1		*FRONT FENDER O/S	Dented/Bent	720.10 FL	*545.30 FL
15	1		*FRONT FENDER BRACKET O/S	Not Necessary	67.20 FL	*- FL
16	1		*FRONT FENDER INNER SHIELD O/S (TORN)	Not Consistent With The Impact	195.40 FL	*- FL
17	1		*FRONT FENDER EMBLEM	Necessary	68.10 FL	*45.00 FL
18	1		*FRONT BONNET	Bent/Buckled	780.50 FL	*688.10 FL
19	1		*FRONT BONNET RUBBER	Not Necessary	78.00 FL	*- FL
20	1		*FRONT BONNET LOCK	Not Necessary	295.60 FL	*- FL
21	1		*FRONT SUPPORT PANEL TOP GARNISH	Twisted	98.50 FL	*98.50 FL
22	1		*FRONT SUPPORT PANEL	Repair	894.00 FL	*- FL
23	1		*CENTRE BRACE PANEL	Not Necessary	195.40 FL	*- FL
24	1		*FRONT LOWER ARM O/S	Not Necessary	789.90 FL	*- FL
25	1		*FRONT KNUCKLE ARM O/S	Not Necessary	496.50 FL	*- FL
26	1		*FRONT KNUCKLE ARM BEARING HUB O/S	Not Necessary	298.40 FL	*- FL
27	1		*FRONT SHOCK ABSORBER O/S	Not Necessary	499.60 FL	*- FL
28	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
29	1		*FRONT RIM O/S (CUT)	Not Consistent With The Impact	680.00 FS	*- FS
30	1		*FRONT TYRE O/S	Not Necessary	280.00 FS	*- FS
31	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,298.60 3,648.10
- List Item Discount on L Items 25.00/25.00% (\$\$) 2,309.65 899.53

Total Parts (\$\$) 7,988.95 2,748.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REPAIR & RENEW ON AFFECTED ACCIDENT AREAS	New	1,200.00	500.00
2	TO PUTTY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	700.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO CONDUCT WHEEL ALIGNMENT	New	180.00	0.00
5	TO REMOVE & RENEW TYRE/RIMS,BALANCING	New	120.00	0.00
6	TO REMOVE & RENEW FRONT O/S UNDERCARRIAGE COMPONENTS	New	250.00	0.00
7	TO CONDUCT ECU SETTING & RESET TO SPECIFICATION	New	450.00	0.00
8	TO RUST PROOF AFFECTED AREAS	New	150.00	60.00
Gross Labour Cost (\$\$)			3,800.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >