

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC4/AIG20013463/T1GS3Q2  
**Date:** 20/08/2021

**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900142670
<b>Claimant Vehicle No :</b>	SHC2783A	<b>Insured Vehicle No :</b>	SJT646M
Date of Loss:	05/12/2020	Nature of Claim:	TP
		Claim No:	0943787711SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHC2783A</b>	Engine No:	G4LEKU402403
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVLU188094
Reg. Date:	07/11/2019 (Man. Year: 2019)	Odometer:	83833 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	926.12	558.60	367.52	39.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	720.00	550.00	170.00	23.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,646.12</b>	<b>1,108.60</b>	<b>537.52</b>	<b>32.65</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>115.23</b>	<b>77.60</b>	<b>37.63</b>	<b>32.66</b>

<b>Nett Amount (S\$)</b>	<b>1,761.35</b>	<b>1,186.20</b>	<b>575.15</b>	<b>32.65</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$125.19/day) (S\$)</b>		375.57		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,713.77</b>		

INSPECTION

Date of Assignment: 07/12/2020

Date Inspected: 07/12/2020

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -RR BUMPER	Repair	459.40 FL	*- FL
2	10		*HYUNDAI BUMPER COVER CLIP	Necessary	22.00 FL	*22.00 FL
3	1		*MOULDING ASSY -R	Deformed	451.25 FL	*451.25 FL
4	1		*HYUNDAI REVERSE SENSOR AS	Not Working	180.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>1,112.65</b>	<b>653.25</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	186.53	94.65
<b>Total Parts (\$)</b>	<b>926.12</b>	<b>558.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	320.00
2	SPRAYPAINT ON AFFECTED AREA	New	250.00	200.00
3	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>720.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >