

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20013466/R1VD3Q2

Date: 25/01/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SLX8079C

Insured Vehicle No : YQ2003T

Date of Loss: 03/12/2020

Nature of Claim: TP

Claim No: CDMCG20001813

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX8079C**

Make & Model: KIA CERATO, 1.6 (A)

Engine No: G4FGJU150520

Reg. Date: 12/04/2018 (Man. Year: 2018)

Chassis No: KMHD841CMJU645950

Colour: Black

Odometer: 732532 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,303.39	2,236.85	66.54	2.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	1,090.00	820.00	42.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,213.39	3,326.85	886.54	21.04
+ GST 7.00/7.00% (S\$)	294.94	232.88	62.06	21.04
Nett Amount (S\$)	4,508.33	3,559.73	948.60	21.04

INSPECTION

Date of Assignment: 07/12/2020

Date Inspected: 16/12/2020

Inspected At:

Avantage Vag (HQ)

48 Toh Guan Road East

Singapore 608586

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2021)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX8079C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,017.27 FL	*1,017.27 FL
2	1		*LH HINGE	Bent	45.68 FL	*45.68 FL
3	1		*RH HINGE	Serviceable	45.68 FL	*- FL
4	1		*FRONT BUMPER	Torn	432.07 FL	*432.07 FL
5	1		*LH BRACKET	Necessary	32.47 FL	*32.47 FL
6	1		*FRONT GRILLE	Cracked	324.13 FL	*324.13 FL
7	1		*FRONT LOGO	Missing	25.21 FL	*25.21 FL
8	1		*TOP GARNISH ,FRONT GRILLE	Cracked	72.45 FL	*72.45 FL
9	1		*TOP STRIP ,FRONT GRILLE	Cut	39.62 FL	*39.62 FL
10	1		*LH HEADLIGHT	Cracked	756.96 FL	*756.96 FL
11	1		*LH REINFORCEMENT ,HEADLIGHT	Cracked	25.20 FL	*25.20 FL
12	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,866.74	2,791.06
- List Item Discount on L Items 20.00/20.00% (\$\$)	563.35	554.21
Total Parts (\$\$)	2,303.39	2,236.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIT BONNET ,HINGE ,FRONT BUMPER ,GRILLE ,LH HEADLIGHT AND OTHER ASSOCIATED COMPONENTS	New	800.00	500.00
2	SURFACE PREPARATION ,SPRAY PAINT AND POLISH BONNET ,HINGE ,FRONT BUMPER AND OTHER AFFECTED AREAS	New	1,000.00	500.00
3	DIANOSTIC CHECK AND ARASE FAULT CODES AFTER THE REPAIR	New	80.00	60.00
4	TUFF KOTE	New	30.00	30.00
Gross Labour Cost (S\$)			1,910.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >