

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20013468/UQF3Q2**Date:** 30/12/2020**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00071902004

Claimant Vehicle No : GBJ176A **Insured Vehicle No :** GBE569B

Date of Loss: 28/11/2020 Nature of Claim: TP Claim No: SNM20D204692/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ176A**
 Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M) Engine No: 1KD2829986
 Reg. Date: 26/11/2018 (Man. Year: 2018) Chassis No: JTFHT02P800245981
 Colour: White Odometer: 94081 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Austone 7 mm Rear Left Side: Austone 7 mm
 Front Right Side: Austone 7 mm Rear Right Side: Austone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,114.05	6,962.04	6,152.01	46.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	2,280.00	1,200.00	34.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,594.05	9,242.04	7,352.01	44.31
Approved Total (Overridden) (S\$)		7,300.00		
(S\$)	16,594.05	7,300.00	9,294.05	56.01
+ GST 7.00/7.00% (S\$)	1,161.58	511.00	650.58	56.01
Nett Amount (S\$)	17,755.63	7,811.00	9,944.63	56.01

INSPECTION

Date of Assignment: 10/12/2020

Date Inspected: 07/12/2020 Inspected At:

Liu's Brother Auto (HQ)
 No. 1 Kaki Bukit Avenue 6 #01-01
 AutoBay @ Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2020)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ176A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Distorted	872.90 F	*872.90 FL
2	1		*FRONT BONNET TOYOTA MOTIF	Necessary	75.00 F	*75.00 FL
3	1		*FRONT BONNET LOCK	Serviceable	88.90 F	*- FL
4	1		*FRONT GRILLE INNER	Cracked	496.80 F	*496.80 FL
5	1		*FRONT GRILLE TOP	Cut	193.50 F	*193.50 FL
6	1		*FRONT GRILLE CENTRE	Cracked	334.50 F	*334.50 FL
7	1		*FRONT BUMPER	Distorted	796.80 F	*606.10 FL
8	1		*FRONT BUMPER CENTRE GRILLE	Torn	162.65 F	*162.65 FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	485.90 F	*- FL
10	1		*FRONT BUMPER TOP RETAINER	Not Necessary	189.60 F	*- FL
11	1		*FRONT SUPPORT PANEL	Repair	434.80 F	*- FL
12	1		*FRONT WIPER GARNISH	Distorted	80.50 F	*80.50 FL
13	1		*FRONT AIRCON HEATER ASSY	Cracked	1,466.10 F	*1,466.10 FL
14	1		*FRONT LH BUMPER SIDE FOG LAMP COVER	Torn	186.00 F	*86.50 FL
15	1		*FRONT LH BONNET HINGE	N/s Twisted	590.60 F	*166.10 FL
16	1		*FRONT LH BUMPER SIDE HOLDER	Cracked	380.40 F	*380.40 FL
17	1		*LH HEAD LAMP	Broken	930.70 F	*707.10 FL
18	1		*FRONT LH CORNER PANEL	Bent	376.50 F	*376.50 FL
19	1		*FRONT LH WIRE HARNESS	Cracked/Torn	1,885.10 F	*1,885.10 FL
20	1		*FRONT LH INNER WIRE HARNESS COVER	Cracked	121.10 F	*121.10 FL
21	1		*FRONT LH WASHER TANK	Distorted	382.60 F	*382.60 FL
22	1		*FRONT LH DOOR	Repair	1,632.50 F	*- FL
23	1		*FRONT LH DOOR OUTER PILLAR	Badly Dented	722.60 F	*722.60 FL
24	1		*FRONT LH DOOR ROC STICKER	Necessary	48.00 FS	*30.00 FS
25	1		*SET FRONT GRILLE CLIP	Necessary	30.00 FS	*30.00 FS
26	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
27	1		*FRONT NUMBER PLATE METAL	Scratched	35.00 FS	*15.00 FS
28	1		*SET LH HEAD LAMP CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,114.05	9,241.05
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	2,279.01
Total Parts (\$\$)	13,114.05	6,962.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	100.00	60.00
3	REMOVE & REINSTALL DASHBOARD, METER INSTRUMENTS, DISCONNECT WIRING & ETCS	New	250.00	200.00
4	TO REMOVE, REPLACE AND TRANSFER DOOR PANEL, FITTING AND MECHANISMS	New	80.00	0.00
5	TO REMOVE & REFIX AIR CON, RE-FILL AIR CON GAS & TEST FOR LEAKAGES	New	200.00	100.00
6	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	1,500.00	1,000.00
7	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	1,300.00	900.00
Gross Labour Cost (\$\$)			3,480.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >