

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20013470/R1BS3Q2

Date: 30/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900245570

Claimant
Vehicle No : SGN980P **Insured Vehicle No :** SCG238J

Date of Loss: 04/12/2020 Nature of Claim: TP Claim No: 7181068515SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGN980P		
Make & Model:	BMW 730LI, 3.0 D/AB 4DR SR LED DSC NAV HUD (A)	Engine No:	10818508N52B30AF
Reg. Date:	19/02/2014 (Man. Year: 2013)	Chassis No:	WBAYE22010DZ21047
Colour:	Black	Odometer:	128309 km
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50 R18	Rear Tyre Size:	245/50 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,801.25	4,956.80	844.45	14.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,146.00	3,994.00	1,152.00	22.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,947.25	8,950.80	1,996.45	18.24
+ GST 7.00/7.00% (S\$)	766.31	626.56	139.75	18.24
Nett Amount (S\$)	11,713.56	9,577.36	2,136.20	18.24
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 08/12/2020

Date Inspected: 08/12/2020 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	*Check	150.00 FS	* - FS
2	1		*FRT LH DOOR	Bent	2,229.20 FS	*2,229.20 FS
3	1		*FRT LH FENDER	Bent	1,236.65 FS	*1,236.65 FS
4	1		*LH TRIM ELEMENT	*Check	78.85 FS	* - FS
5	1		*LH OUTSIDE MIRROR W/OUT GLASS	Scratched	1,490.95 FS	*1,490.95 FS
6	1		*LH MIRROR COVER PRIMED	Repair	142.75 FS	* - FS
7	1		*(S/L) FRT DOOR WEATHERSTRIP	*Check	226.25 FS	* - FS
8	1		*FRT LH DOOR ROOF SEAM SEAL	*Check	152.40 FS	* - FS
9	1		*(S/L) FRT LH DOOR A JOINT GASKET	*Check	94.20 FS	* - FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 5,801.25 4,956.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT LH FENDER ,FRONT LH DOOR & ALL ATTACHMENT ITEMS CASUE BY ACCIDENT	New	2,550.00	1,700.00
2	TO SPRAY PAINT FRONT LH FENDER ,FRONT LH DOOR	New	1,770.00	1,593.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECK ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	451.00
5	TO CARRY OUT BODY CAVITYPRESER VATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (\$\$)			5,146.00	3,994.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >