

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG20013477/EQF3E2

Date: 12/01/2021

REFERENCE

Insured/Claimant:	NG KAI KHUAY	Policy No:	1800109859		
Date of Loss:	01/12/2020	Nature of Claim:	OD	Claim No:	4423794632SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBB3716P		
Make & Model:	MITSUBISHI ECLIPSE CROSS, 1.5 CVT (A)	Engine No:	4B40DN9040
Reg. Date:	13/09/2018 (Man. Year: 2018)	Chassis No:	JMAXTGK1WJZ002613
Colour:	Brown	Odometer:	29629 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	S\$88,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/70R15	Rear Tyre Size:	215/70R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,782.98	2,862.84	920.14	24.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,560.00	2,530.00	3,030.00	54.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,342.98	5,392.84	3,950.14	42.28
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	8,942.98	4,992.84	3,950.14	44.17
+ GST 7.00/7.00% (S\$)	626.01	349.50	276.51	44.17
Nett Amount (S\$)	9,568.99	5,342.34	4,226.65	44.17

INSPECTION

Date of Assignment:	07/12/2020		
Date Inspected:	07/12/2020	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	6.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER,FR LH	Repair	599.00 FL	*- FL
2	1		*MOULDING,FR WHEEL ARCH,LH	Cut	151.00 FL	*151.00 FL
3	1		*PANEL ASSY,FR DOOR,LH	Dented	949.00 FL	*949.00 FL
4	1		*MOULDING,F/DR SASH,UPR LH	Necessary	119.00 FL	*119.00 FL
5	1		*MLDG,F/DR WDO BELT LINE,LH	Not Necessary	89.00 FL	*- FL
6	1		*GARNISH,FR DOOR,LH	Cut	174.00 FL	*174.00 FL
7	1		*GARNISH,FR DOOR SASH,LH	Necessary	66.00 FL	*66.00 FL
8	1		*PANEL ASSY,RR DOOR,LH	Dented	937.00 FL	*937.00 FL
9	1		*MOULDING,R/DR SASH,UPR LH	Necessary	114.00 FL	*114.00 FL
10	1		*MLDG,R/DR WDO BELT LINE,LH	Not Necessary	120.00 FL	*- FL
11	1		*GARNISH,RR DOOR,LH	Cut	102.00 FL	*102.00 FL
12	1		*GARNISH,RR DOOR SASH,FR LH	Not Necessary	108.00 FL	*- FL
13	1		*GARNISH,RR DOOR SASH,RR LH	Not Necessary	49.00 FL	*- FL
14	1		*GARNISH,SIDE SILL,LH	Not Necessary	91.00 FL	*- FL
15	1		*MOULDING,R/DOOR PROTECT,LH	Cut	105.00 FL	*105.00 FL
16	1		*MOULDING,RR WHEEL ARCH,LH	Cut	153.00 FL	*153.00 FL
17	1		*SHIELD,RR WHEEL,FR LH	Not Necessary	126.00 FL	*- FL
18	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
19	1		*VALVE TIRE (SUPPLEMENTARY)	Necessary	39.00 FL	*39.00 FL
20	1		*WHEEL,DISC	Cut	783.00 FL	*783.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,904.00	3,712.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,121.02	849.16
Total Parts (\$\$)	3,782.98	2,862.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW LHF FENDER,LHF DOOR & LHR DOOR.REPAIR LHR FENDER & RR BUMPER	New	2,250.00	900.00
2	RESPRAY FR BUMPER,LHF FENDER,LHF DOOR,LHR DOOR,LHR FENDER & RR BUMPER	New	2,100.00	1,050.00
3	REMOVE & REFIT LHF DOOR COMPONENT	New	120.00	120.00
4	REMOVE & REFIT LHR DOOR COMPONENT	New	120.00	120.00
5	RENEW LHF SPORT RIM & TRANSFER TYRE	New	30.00	0.00
6	RENEW LHR SPORT RIM & TRANSFER TYRE	New	30.00	30.00
7	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	APPLY ANTI CORROSION ON AFFECTED	New	80.00	40.00
10	REMOVE & REFIT REVERSE SENSOR	New	80.00	0.00
11	TO CONDUCT COMPUTIRIZE FULL WHEEL ALIGNMENT (SUPPLEMENTARY)	New	120.00	120.00
12	SUPPLY LHF SPORT RIM	New	480.00	-
Gross Labour Cost (S\$)			5,560.00	2,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >