

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20013478/R1BS3Q2

Date: 12/05/2021

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	SMT9057T	<b>Insured Vehicle No :</b>	SH8071A
Date of Loss:	06/12/2020	Nature of Claim:	TP
		Claim No:	MCT20120095

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMT9057T</b>		
Make & Model:	BMW 216I, 1.5 GRAN TOURER (A)	Engine No:	39305260B38A15A
Reg. Date:	28/09/2018 (Man. Year: 2018)	Chassis No:	WBA6V12030ED04960
Colour:	White	Odometer:	65675 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,739.70	323.55	3,416.15	91.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,838.00	2,272.00	566.00	19.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>6,577.70</b>	<b>2,595.55</b>	<b>3,982.15</b>	<b>60.54</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>460.44</b>	<b>181.69</b>	<b>278.75</b>	<b>60.54</b>
<b>Nett Amount (\$\$)</b>	<b>7,038.14</b>	<b>2,777.24</b>	<b>4,260.90</b>	<b>60.54</b>
<b>+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (\$\$)</b>		<b>214.00</b>		
	<b>Nett Liability (\$\$)</b>	<b>2,991.24</b>		

### INSPECTION

Date of Assignment:	28/12/2020	
Date Inspected:	28/12/2020 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: CHUA ZHEN LI

5/12/2021

Adjuster Report

*any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2021)
<b>Parts:</b>	M1-MPV	BMW 216I 1.5 GRAN TOURER (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMT9057T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*40.00 FS
2	1		*FRT BUMPER LH INSERT	Serviceable	10.65 FS	*- FS
3	1		*FRT BUMPER RH INSERT	Not Necessary	10.85 FS	*- FS
4	1		*FRT LH SIDE PANEL TOP MOULDING	Serviceable	9.80 FS	*- FS
5	1		*FRT RH SIDE PANEL TOP MOULDING	Not Necessary	9.85 FS	*- FS
6	1		*LH FOG LAMP SUPPORT	Serviceable	78.00 FS	*- FS
7	1		*LH FINISHER	Scratched	49.90 FS	*49.90 FS
8	1		*LH MOLDING (SPORT)	Scratched	67.00 FS	*67.00 FS
9	1		*FRT BUMPER PRIMED PANEL (PMA)	Repair	897.25 FS	*- FS
10	1		*LH GRID LATERAL (LINES/PDC)	Scratched	95.05 FS	*95.05 FS
11	1		*PLAQUE 82MM	Necessary	71.60 FS	*71.60 FS
12	1		*LH HEADLIGHT LED TECHNOLOGY	Serviceable	2,359.75 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>3,739.70</b>	<b>323.55</b>
--------------------------	-----------------	---------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE FRONT BUMPER INCLUDE REMOVE ATTACHMENT ETC	New	1,275.00	840.00
2	PAINTING FRONT BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	150.00
4	PAINT PROTECTION AUTO PREMIUM CERAMIC 9H COAT	New	348.00	348.00
Gross Labour Cost (\$\$)			<b>2,838.00</b>	<b>2,272.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >