#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Nature of Claim:

Our File No:

ΤP

CS3/AIG20013485/T1TF3E2

Date:

05/01/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070092924

**Claimant Vehicle No** 

SMJ3762H 06/12/2020 Insured Vehicle No: GBF1135H

> Claim No: 7537428730SG

> > 149272 km

Yes

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SMJ3762H

Make & Model: HONDA FREED HYBRID, 1.5 G (A) Reg. Date: 01/03/2019 (Man. Year: 2018) Colour:

Engine No: LEB5621969 Chassis No: GB71084576

**Engine Capacity:** 

Blue 1496 cc N/A

Market Value/New Car Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Footbrake (Serviceable): Pre-accident Condition:

Rear Right Side:

Nο

Handbrake (Serviceable): **Engine Modification:** Yes

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

185/65R15 Rear Tyre Size: Rear Left Side:

185/65R15

Dunlop 6 mm

Dunlop 6 mm Front Right Side: Dunlop 6 mm Dunlop 6 mm

Odometer:

The above values represent the remaining tyre treads depth

| COST OF CLAIMS      | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------|------------|------------|--------|
| Parts               | 0.00       | 0.00       | 0.00       |        |
| Miscellaneous Items | 0.00       | 0.00       | 0.00       |        |
| Labour              | 0.00       | 0.00       | 0.00       |        |
| Paintwork Labour    | 0.00       | 0.00       | 0.00       |        |
| Towing              | 0.00       | 0.00       | 0.00       |        |
| Nett Amount (S\$)   | 0.00       | 0.00       | 0.00       |        |

**INSPECTION** 

Date of Assignment:

07/12/2020

Apex Motoring

Date Inspected:

Adjuster:

08/12/2020

Inspected At:

25 Kaki Bukit Road 4, #01-55 Synergy @ KB

Singapore 417800

Estimated Period of Repair:

4.0 days

MOHD TAUFIKH BIN HAMID

Manager:

DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

## **Recommended Parts**

| No.   | Qty     | Part No. | Particulars                  | Condition              | Repairer's | Amount |
|-------|---------|----------|------------------------------|------------------------|------------|--------|
| 1     | 1       |          | *FRT BUMPER                  | Deformed               | 0.00 F     | *- F   |
| 2     | 1       |          | *FRT BUMPER CLIPS            | Necessary              | 0.00 F     | *- F   |
| 3     | 1       |          | *FRT BUMPER SIDE RETAINER RH | Necessary              | 0.00 F     | *- F   |
| 4     | 1       |          | *FRT HEADLAMP RH             | * Check                | 0.00 F     | *- F   |
| 5     | 1       |          | *FRT RH FENDER               | Repair                 | 0.00 F     | *- F   |
| 6     | 1       |          | *FRT RH FENDER INNER SHIELD  | * Check                | 0.00 F     | *- F   |
| F=Fra | anchise | part.    |                              | ,                      |            |        |
|       |         |          |                              | Total Parts (S\$)      | 0.00       | 0.00   |
|       |         |          | Report was unsubmitted       | during this print-out. |            |        |

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >