LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Policy No:

Our File No:

CS3/AIG20013488/GVF3E2

Date:

04/01/2021

Claim No:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

0999993924

Claimant Vehicle No

VBK5018

Insured Vehicle No:

SML3333C

Date of Loss:

02/12/2020

Nature of Claim:

ΤP

7962907907SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Make & Model:

VOLKSWAGEN PASSAT TSI, 1.8 (A) 01/01/2018 (Man. Year: 2018)

Engine No: Chassis No: Odometer:

PPVZZZ3CZHL000372 CJ5177895

37073 km

Reg. Date: Colour:

Black

Engine Capacity:

1798 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable):

Engine Modification: Yes

Pre-accident Condition: Nο

CONDITION OF TYRES

Front Tyre Size:

235/45 R18

Rear Tyre Size:

235/45 R18

Front Left Side: Front Right Side: General 6 mm General 6 mm Rear Left Side:

General 6 mm

Rear Right Side:

General 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

03/12/2020

Carsmith Private Limited (HQ)

Date Inspected:

Adjuster:

08/12/2020

Inspected At:

13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ CENTRE

Singapore 417807

Estimated Period of Repair:

XING GUO QIANG

4.0 days

Manager:

VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Scratched	0.00 F	*-F
2	1		*REAR NUMBER PLATE BASE	Cracked	0.00 F	*- F
3	1		*REAR BUMPER	Deformed	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER BRACKET	Cut	0.00 F	*- F
6	2		*REAR BUMPER SIDE RETAINER	Cut	0.00 F	*- F
7	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*-F
8	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
9	1		*REAR END PANEL	Repair	0.00 F	*-F
10	1		*REAR END PANEL TOP GARNISH	Broken	0.00 F	*- F
11	1		*REAR LH TAILLAMP	Cracked	0.00 F	*-F
12	1		*REAR RH TAILLAMP	Cracked	0.00 F	*-F
13	1		*BOOTLID	Dented	0.00 F	*-F
14	3		*BOOTLID EMBLEM	Necessary	0.00 F	*-F
15	1		*BOOTLID LAMP LH	Cracked	0.00 F	*-F
16	1		*BOOTLID LAMP RH	Cracked	0.00 F	*-F
17	1		*BOOTLID RUBBER	Twisted	0.00 F	*-F
F=Fra	ınchise	part.				
				Total Parts (S\$)	0.00	0.00
				_		
			Report was unsubmitted	during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >