



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2104142

36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV Date 14/06/2021  
Reference CC4/FCI20013500/Krs3q2  
Code FCI2

#### PROFESSIONAL SERVICE FEE

Vehicle No. SLA 6407Z  
Insured Veh. SHB 4882P  
Claim No. D20004943MFSH  
Policy No. D-20094921MFSH  
Accident Date 06/12/2020  
Inspection Date 08/12/2020

Description	Total
Third Party Express Settlement	500.00
<b>Subtotal</b>	<b>500.00</b>
<b>GST (7%)</b>	<b>35.00</b>
<b>Grand Total</b>	<b>535.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CC4/FCI20013500/Krs3q2 Date: 14/06/2021 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	SHB 4882P	<b>Veh. Inspected</b>	SLA 6407Z
<b>Policy No.</b>	D-20094921MFSH	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D20004943MFSH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	MERINA	<b>Assign Date</b>	08/12/2020
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	NISSAN X-TRAIL (A)	<b>c.c</b>	1997
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	JN1JANT32Z0001532	<b>Colour</b>	METALLIC DARK GREY
<b>Odometer</b>	56753 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	225/60 R18	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	225/60 R18	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	225/60 R18	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	225/60 R18	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.		
<b>5. General Information</b>			
<b>Accident Date</b>	06/12/2020	<b>Inspection Date</b>	08/12/2020
<b>Survey held at</b>	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		
<b>5a. Remarks</b>			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
<b>5b. Estimate Days of Repair</b>			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 6407Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAIL GATE (N)	CRACKED	4,380.00	4,200.00
1	TAIL GATE W/SCREEN MOULDING TOP (N)	NECESSARY	126.00	126.00
1	TAIL GATE W/SCREEN MOULDING BOTTOM (N)	NECESSARY	89.50	89.50
2	TAIL GATE W/SCREEN MOULDING SIDE @\$86.00 (N)	NECESSARY	172.00	172.00
1	REAR BUMPER (N)	BUCKLED / DENTED	693.50	693.50
1	REAR BUMPER TOP CHROME (N)	DENTED	469.10	469.10
2	REAR BUMPER SIDE RETAINER @\$38.90 (N)	SERVICEABLE	77.80	-
2	REAR BUMPER BRACKET @\$195.60 (N)	TO REPAIR SEE LABOUR	391.20	-
10	REAR BUMPER CLIP @\$5.50 (N)	NECESSARY	44.00	44.00
1	REAR BUMPER BEAM (N)	TO REPAIR SEE LABOUR	596.40	-
1	REAR BUMPER SPONGE (N)	SERVICEABLE	147.50	-
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	487.50	-
1	REAR END PANEL TOP GARNISH (N)	SERVICEABLE	492.80	-
1	REAR FENDER GARNISH R/H (N)	SERVICEABLE	211.00	-
1	REAR FENDER GARNISH L/H (N)	SERVICEABLE	211.00	-
1	REAR END PANEL LOWER (N)	DENTED	385.00	385.00
1	REAR BUMPER CENTRE GRILLE (N)	CRACKED	135.00	135.00
	LESS 10% DISCOUNT		-910.93	-631.41
			<b>8,198.37</b>	<b>5,682.69</b>
<b><u>SPECIAL NETT ITEMS</u></b>				
1	TAIL GATE W/SCREEN SEALANT (SN)	NECESSARY	226.10	40.00
4	REVERSE SENSOR @\$280.00 (SN)	DENTED	1,120.00	250.00
1	REAR NUMBER PLATE (SN)	SERVICEABLE	25.00	-
			<b>1,371.10</b>	<b>290.00</b>
<b><u>LABOUR</u></b>				
	SPRAY PAINT DAMAGED AREA AFFECTED .		1,600.00	750.00
	RUST PROOFING TREATMENT .	NOT NECESSARY	100.00	-



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TRANSFER TAILGATE COMPONENT TO NEW GATE .		150.00	60.00
	CHANGE TAIL LAMP AND CHECK WIRING.		65.00	20.00
	REMOVE & REINSTALL REAR W/SCREEN GLASS .		180.00	120.00
	TO CUT OFF REAR END PANEL ,KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET,REAR BUMPER BEAM AND REAR END PANEL.		1,200.00	500.00
			3,295.00	1,450.00
	<b>GRAND TOTAL</b>		<b>12,864.47</b>	<b>7,422.69</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,900.00</b>
---	--	--	--	-----------------

Report Ref No. CC4/FCI20013500/Krs3q2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SLA 6407Z

## INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SLA 6407Z**

**RE-INSPECTION**





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SLA 6407Z**

**RE-INSPECTION**

