

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013501/DBS3Q2

Date: 05/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070141371
Claimant		
Vehicle No : SLT7787U	Insured Vehicle No :	SMV4702L
Date of Loss: 04/12/2020	Nature of Claim: TP	Claim No: 6397765260SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT7787U	Engine No:	GD43309
Make & Model:	FORD FOCUS, 999cc Titanium (A)	Chassis No:	WF04XXGCC4GD43309
Reg. Date:	12/10/2017 (Man. Year: 2016)	Odometer:	55636 km
Colour:	Brown		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,160.00	5,239.30	18,920.70	78.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	1,180.00	2,420.00	67.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,760.00	6,419.30	21,340.70	76.88
Approved Total (Overridden) (S\$)		5,100.00		
(S\$)	27,760.00	5,100.00	22,660.00	81.63
+ GST 7.00/7.00% (S\$)	1,943.20	357.00	1,586.20	81.63
Nett Amount (S\$)	29,703.20	5,457.00	24,246.20	81.63
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
(S\$)		5,992.00		
Liabile Amount (50.00%) (S\$)		2,996.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		3,032.45		
Global Sum Settlement (S\$)		3,000.00		

INSPECTION

Date of Assignment:	08/12/2020	
Date Inspected:	09/12/2020 Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A,, #03-

08 AMK AutoPoint
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	2,986.00 FL	*- FL
2	1		*BONNET INSULATOR	Not Necessary	294.00 FL	*- FL
3	2		*BONNET HINGE LH/RH	Not Necessary	336.00 FL	*- FL
4	1		*HEAD LAMP LH/RH	O/S MtgCracked/N/SNotNecessary	7,780.00 FL	*2,603.70 FL
5	1		*HEAD LAMP LOWER BRACKET LH/RH	O/S Cracked / N/SNot Necessary	420.00 FL	*210.00 FL
6	1		*FRONT BUMPER	Distorted	2,780.00 FL	*1,377.00 FL
7	2		*FRONT BUMPER SIDE RETAINER LH/RH	Serviceable	380.00 FL	*- FL
8	1		*FRONT BUMPER GRILLE	Serviceable	580.00 FL	*- FL
9	1		*FRONT BUMPER GRILLE BASE	Serviceable	510.00 FL	*- FL
10	1		*FRONT BUMPER GRILLE CHROME	Mtg Cracked	485.00 FL	*485.00 FL
11	1		*FRONT BUMPER HEAD LAMP NOZZLE CAP RH	Not Necessary	109.00 FL	*- FL
12	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	95.00 FL	*- FL
13	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	468.00 FL	*- FL
14	1		*FRONT BUMPER FOG LAMP GARNISH RH	Distorted	210.00 FL	*210.00 FL
15	1		*FRONT BUMPER FOG LAMP CHROME RH	Not Necessary	220.00 FL	*- FL
16	1		*FRONT BUMPER FOG LAMP HOLDER RH	Not Necessary	195.00 FL	*- FL
17	1		*FRONT BUMPER FOG LAMP WIRE HARNESS	Not Necessary	1,850.00 FL	*- FL
18	1		*FRONT BUMPER LOWER LID	Cut	1,680.00 FL	*891.30 FL
19	1		*FRONT BUMPER UNDER COVER	Not Necessary	450.00 FL	*- FL
20	1		*WIPER WASHER TANK	Not Necessary	410.00 FL	*- FL
21	1		*WIPER WASHER TANK MOTOR	Not Necessary	229.00 FL	*- FL
22	1		*WIPER WASHER TANK HOSE	Not Necessary	150.00 FL	*- FL
23	1		*FRONT FENDER RH	Not Necessary	1,723.00 FL	*- FL
24	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	231.00 FL	*- FL
25	1		*SUPPORT PANEL	Repair	1,829.00 FL	*- FL
26	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
27	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
28	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
29	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
30	1		*FRONT BUMPER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
31	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
32	1		*FRONT BUMPER LOWER LID CLIPS	Not Necessary	50.00 FS	*- FS
33	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	26,800.00	5,817.00
- List Item Discount on L Items 10.00/10.00% (\$)	2,640.00	577.70
Total Parts (\$)	24,160.00	5,239.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,400.00	600.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,400.00	400.00
3	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
4	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
5	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
Gross Labour Cost (S\$)			3,600.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >