

REPAIR ESTIMATE\*

VEHICLE NO SHA1944U

04/12/20

MAKE :

MODEL IONIQ G2

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$459.40
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER STAY LH /RH		\$138.10	\$276.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER FOG LAMP			\$201.50
1	REAR NUMBER PLATE LAMP LH/RH		\$85.30	\$170.60
1	REAR BUMPER BRACKET RH/ LH		\$55.80	\$111.60
	Supp Antenna usg - smart key can ✓		40.50	\$2,087.35
	20.00% DISCOUNTED TOTAL		1644.15	\$417.47
			20% - 1315.32	\$1,669.88
1	REAR NUMBER PLATE W/HOLDER			\$55.00
1	REAR REVERSE SENSOR		235	\$180.00
		10.00%	→ 211.50	\$261.50
	<b>Labour Charge</b>			
	Panel Beating		320	\$640.00
	Spray Painting Charge		200	\$500.00
	Tuff Kote		un X	\$60.00
	Diagnose/ reset error code		150 un X	\$300.00
	Remove/Refix reverse sensor		30	\$60.00
	<b>TOTAL LABOUR</b>		550	\$1,560.00
	<b>ESTIMATE TOTAL</b>		2076.82	\$3,491.38
			4541650 X	
			2 days	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495449 Daunt  
 WP' 9/17/2021 pm  
 2 days  
 4/5 Resurvey after repair  
 Tanpin e lkhankon