### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EQI20013505/T1TF3E2

28/12/2020 Date:

**REFERENCE** 

Handling Insurer: **EQ Insurance Company Ltd** 

Policy No: DMPPHQ20-000115

**Claimant Vehicle** 

SH9072R

Insured Vehicle No: SKD7785X

No: 05/12/2020 Date of Loss:

Nature of Claim: TP Claim No: DM20HO01832

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SH9072R

HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Make & Model:

Engine No: G4LEKU408596

Reg. Date: 19/12/2019 (Man. Year: 2019) Chassis No: KMHC851CVLU189822 Odometer: 138728 km

Colour: Blue 1580 cc

**Engine Capacity:** 

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: West Lake 6 mm West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,212.92	155.00	3,057.92	95.18
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,140.00	720.00	420.00	36.84
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	4,352.92	875.00	3,477.92	79.90
	+ GST 7.00/7.00% (S\$)	304.70	61.25	243.45	79.90
	Nett Amount (S\$)	4,657.62	936.25	3,721.37	79.90

**INSPECTION** 

Date of Assignment: 08/12/2020 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 08/12/2020 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

MOHD TAUFIKH BIN HAMID DENISE TAY KWEE CHENG Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Dec 2020)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SH9072R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR ASSY	Repair	1,797.20 FL	*- FL
2	1		*REAR RH DOOR ASSY	Repair	1,789.90 FL	*- FL
3	1		*FRT DOOR COMFORTDELGRO LOGO	Cut	75.00 F	*75.00 F
4	1		*REAR DOOR APPS LOGA	Cut	80.00 F	*80.00 F
5	1		*FRT RH DOOR PROTECTOR	Repair	110.00 FL	*- FL
6	1		*REAR RH DOOR PROTECTOR	Repair	125.30 FL	*- FL
F=Fra	anchise	part. L=ListIte	mDisc.	,		
				Sub Total (S\$)	3,977.40	155.00
			- List Item Discount on L Items 2	20.00/20.00% (S\$)	764.48	0.00
				Total Parts (S\$)	3,212.92	155.00
				_		

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	400.00	320.00
2	SPRAYPAINT	New	500.00	400.00
3	TRANSFER DOOR PARTS	New	240.00	0.00
		Gross Labour Cost (S\$)	1,140.00	720.00
	Repo	ort was unsubmitted during this print-out.		

< END OF ESTIMATES >