

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20013514/AQD3N2**Date:** 18/11/2021**REFERENCE**

Insured/Claimant:	LIM POR WAH	Policy No:	1900191325-01	
Date of Loss:	19/11/2020	Nature of Claim:	OD	Claim No: 6935463286SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP7725H		
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Engine No:	CVK086883
Reg. Date:	15/10/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF45KA110726
Colour:	Grey	Odometer:	11590 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$136,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,237.00	6,154.40	2,082.60	25.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,022.00	1,492.00	3,530.00	70.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,259.00	7,646.40	5,612.60	42.33
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	12,159.00	6,546.40	5,612.60	46.16
+ GST 7.00/7.00% (S\$)	851.13	458.25	392.88	46.16
Nett Amount (S\$)	13,010.13	7,004.65	6,005.48	46.16

INSPECTION

Date of Assignment:	08/12/2020		
Date Inspected:	08/12/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LED HEADLIGHT-LH	Cut	7,693.00 FS	*6,154.40 FS
2	1		*LIFT CYLINDER-LH	Not Necessary	208.00 FS	*- FS
3	1		*BONNET IMPACT PROTECTION-CENTRE	Not Necessary	27.00 FS	*- FS
4	1		*BONNET IMPACT PROTECTION-LH	Not Necessary	28.00 FS	*- FS
5	1		*BONNET IMPACT PROTECTION-RH	Not Necessary	27.00 FS	*- FS
6	1		*TOP FENDER LEDGE COVER-UPPER	Not Necessary	31.00 FS	*- FS
7	1		*TOP FENDER LEDGE COVER-LOWER	Not Necessary	23.00 FS	*- FS
8	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					8,237.00	6,154.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	280.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE FRONT BUMPER.TO RENEW LHS HEADLIGHT.TO REPAIR LHS FRONT FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,400.00	500.00
4	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER AND BONNET	New	2,800.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,022.00	1,492.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >