

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20013518/R1QD3E2

Date: 02/07/2021

REFERENCE

Insured/Claimant: DOUBLE TRANS PTE LTD Policy No: DMCVSNA00005742000

Date of Loss: 26/11/2020

Nature of Claim: OD

Claim No: SNM20D204628C01/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE5495L**

Make & Model: HINO FS1EKND, 12.9 D 28 TON 6X4 MT (M)

Engine No: E13CAT10536

Reg. Date: 23/01/2020 (Man. Year: 2019)

Chassis No: JHDFS1EKNXXX10048

Colour: White

Odometer: 32481 km

Engine Capacity: 12913 cc

Market Value/New Car Price: S\$140,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 8/8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	78,069.40	36,379.80	41,689.60	53.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	31,359.20	21,679.20	9,680.00	30.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	109,428.60	58,059.00	51,369.60	46.94
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	107,928.60	56,559.00	51,369.60	47.60
+ GST 7.00/7.00% (S\$)	7,555.00	3,959.13	3,595.87	47.60
Nett Amount (S\$)	115,483.60	60,518.13	54,965.47	47.60

INSPECTION

Date of Assignment: 08/12/2020

Date Inspected: 08/12/2020 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)

2 Pandan Crescent

Singapore 128462

Estimated Period of Repair: 20.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Jul 2021)	
Parts:	N/A	HINO FS1EKND 12.9 D 28 TON 6X4 MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE5495L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*SEALANT	Necessary	500.00 FS	*300.00 FS
3	1		*BUMPER SUB-ASSY, FR	Bent	2,265.00 FS	*2,265.00 FS
4	1		*EXTENSION SUB-ASSY, FR BUMPER, LH	Bent	237.10 FS	*237.10 FS
5	1		*BRACKET SUB-ASSY, HE	Bent	202.60 FS	*202.60 FS
6	1		*STAY, HEADLAMP, NO.2	Missing	49.30 FS	*49.30 FS
7	1		*GARNISH, BUMPER, LH	Distorted	172.10 FS	*172.10 FS
8	1		*GARNISH, BUMPER, LH	Serviceable	154.90 FS	*- FS
9	1		*MOULDING, FR BUMPER	Distorted	17.00 FS	*17.00 FS
10	1		*REINFORCE, FR BUMPER	Bent	267.00 FS	*267.00 FS
11	1		*BRACKET, GRILLE	Bent	29.50 FS	*29.50 FS
12	1		*GRILLE SUB-ASSY, RAD	Missing	1,023.10 FS	*1,023.10 FS
13	1		*STAY SUB-ASSY, FR UN (2PCS)	Bent (1Pc Only)	564.60 FS	*282.30 FS
14	1		*MEMBER, ENGINE COVER	Bent	895.90 FS	*895.90 FS
15	1		*STAY SUB-ASSY, STEP	Bent	155.40 FS	*155.40 FS
16	1		*SUPPORT SUB-ASSY, ST	Bent	711.60 FS	*711.60 FS
17	6		*NUT	Necessary	11.40 FS	*11.40 FS
18	1		*STAY SYB ASSY, STEP	Bent	94.70 FS	*94.70 FS
19	1		*BRACKET, TILT CAB ST	Bent	285.00 FS	*285.00 FS
20	1		*LEVER ASSY, LID LOCK	Distorted	33.00 FS	*33.00 FS
21	1		*REFLECTORASSY, REFLE	Broken	17.00 FS	*17.00 FS
22	1		*LID SUB-ASSY, STEPOP	Bent	114.20 FS	*114.20 FS
23	1		*CONTROLOPENER SUBASS	Cut	89.70 FS	*89.70 FS
24	1		*COVER, STEP, LH	Deformed	384.70 FS	*384.70 FS
25	8		*SCREW, HEX LOBULAR	Necessary	28.80 FS	*28.80 FS
26	2		*NUT, FLANGE	Necessary	3.00 FS	*3.00 FS
27	1		*HOLDER MUDGUARD	Necessary	33.00 FS	*33.00 FS
28	1		*APRON, STEP, LH	Bent	146.20 FS	*146.20 FS
29	1		*MUDGUARD, STEP	Cracked	47.50 FS	*47.50 FS
30	1		*NUT	Necessary	1.50 FS	*1.50 FS
31	1		*BOLT	Necessary	5.30 FS	*5.30 FS
32	1		*COWL	Buckled	2,385.90 FS	*2,385.90 FS
33	1		*PANEL SUB-ASSY, DASH	Repair	1,970.30 FS	*- FS
34	2		*CUSHION, BODY MOUNTI	Serviceable	17.60 FS	*- FS
35	1		*PANEL SUB-ASSY, COWL	Serviceable	1,130.70 FS	*- FS
36	1		*GUSSET, FR BODY PILL	Serviceable	57.50 FS	*- FS
37	1		*PILLAR, FR BODY, LWR	Bent	316.20 FS	*316.20 FS
38	1		*BRACKET, INSTRUMENT	Necessary	8.80 FS	*8.80 FS
39	1		*REINFORCEMENT SUB AS	Serviceable	107.40 FS	*- FS
40	1		*REINFORCEMENT SUB AS	Serviceable	107.40 FS	*- FS
41	1		*GRILLE, RADIATOR	Cracked	2,121.70 FS	*2,121.70 FS
42	1		*EMBLEM	Not Necessary	211.60 FS	*- FS
43	1		*EMBLEM	Not Necessary	211.60 FS	*- FS
44	1		*SEAL, FR PANEL, LWR	Not Necessary	99.90 FS	*- FS
45	1		*WEATHERSTRIP, FR CRNE	Necessary	54.20 FS	*54.20 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*WEATHERSTRIP, FR CONE	Necessary	226.60 FS	*226.60 FS
47	1		*MEMBER, HOOD	Serviceable	50.50 FS	*- FS
48	1		*WEATHERSTRIP, FR CORN	Serviceable	82.70 FS	*- FS
49	1		*SEAL, FR PANEL, LWR RH	Not Necessary	103.40 FS	*- FS
50	1		*SEAL, FR PANEL, LWR LH	Not Necessary	103.50 FS	*- FS
51	2		*STRIKER ASSY, HOOD P	Serviceable	34.60 FS	*- FS
52	1		*STAY ASSY, DUMPER	Serviceable	151.70 FS	*- FS
53	2		*LOCK ASSY, LID	Serviceable	181.40 FS	*- FS
54	2		*HANDLE, LID LOCK	Serviceable	48.00 FS	*- FS
55	1		*REINFORCE SUB-ASSY	Bent	261.80 FS	*261.80 FS
56	1		*EXTENSION, FR FENDER	Cracked	648.00 FS	*648.00 FS
57	1		*PANEL, FR CORNER, LWR	Cracked	14.50 FS	*14.50 FS
58	6		*RETAINER	Necessary	8.40 FS	*8.40 FS
59	1		*PANEL, COWL TOP, OUT	Serviceable	677.60 FS	*- FS
60	1		*ORNAMENT, RADIATOR G	Necessary	276.30 FS	*276.30 FS
61	1		*ORNAMENT, HOOD, LWR	Necessary	185.10 FS	*185.10 FS
62	1		*ORNAMENT, FR FENDER	Necessary	113.70 FS	*113.70 FS
63	1		*ORNAMENT, FR DOOR, R	Necessary	239.80 FS	*239.80 FS
64	1		*CROSSMEMBER SUB ASSY	Serviceable	167.60 FS	*- FS
65	1		*BRACKET SUB ASSY, CTR	Serviceable	103.50 FS	*- FS
66	1		*BRACKET, CTR SEAT, F	Serviceable	121.20 FS	*- FS
67	1		*BRACKET, FOOT REST	Serviceable	17.00 FS	*- FS
68	1		*BRACKET BRACE LH	Serviceable	17.00 FS	*- FS
69	2		*PLATE, FIRE EXTING U	Serviceable	16.60 FS	*- FS
70	1		*PLATE, CTR SEAT GRIP	Serviceable	18.50 FS	*- FS
71	1		*PLATE, CTR SEATBACK S	Serviceable	54.00 FS	*- FS
72	1		*STIFFENER, FLOOR BOAR	Serviceable	515.00 FS	*- FS
73	1		*PANEL, FLOOR, CENTER	Serviceable	861.20 FS	*- FS
74	1		*CLAMP SUB-ASSY, PARK	Serviceable	54.20 FS	*- FS
75	1		*RETAINER, JACK COVER	Serviceable	33.00 FS	*- FS
76	1		*REINFORCEMENT, FLOOR SIDE BMR, NO.1 LH	Bent	320.00 FS	*320.00 FS
77	1		*MEMBER ASSY, FLOOR SIDE, LH	Bent	742.80 FS	*742.80 FS
78	1		*MEMBER, SEAT SET FR,	Bent	131.90 FS	*131.90 FS
79	1		*MEMBER, SEAT SET, RR	Bent	128.70 FS	*128.70 FS
80	1		*BRACKET, BED SET	Necessary	19.30 FS	*19.30 FS
81	1		*PLATE, WASHER TANK S	Necessary	8.30 FS	*8.30 FS
82	1		*GUS SET, WHEELHOUSE	Bent	729.10 FS	*729.10 FS
83	1		*SPLASHBOARD, FR, LH	Serviceable	111.90 FS	*- FS
84	1		*PANEL SUB-ASSY, FR DOOR, LH	Buckled	2,875.20 FS	*2,875.20 FS
85	2		*HINGE ASSY, DOOR	Bent	379.80 FS	*379.80 FS
86	1		*BRACKET, FR DOOR OUT	Bent	149.90 FS	*149.90 FS
87	1		*GARNISH SUB-ASSY, DO	Deformed	250.00 FS	*250.00 FS
88	1		*STOPPER	Necessary	7.80 FS	*7.80 FS
89	5		*BOLT	Necessary	8.00 FS	*8.00 FS
90	1		*SCREW	Necessary	1.60 FS	*1.60 FS
91	1		*SCREW	Necessary	1.40 FS	*1.40 FS
92	1		*PILLAR, FR BODY, UPR	Bent	603.50 FS	*603.50 FS
93	1		*PANEL, QUARTER, LH	Bent	1,046.30 FS	*1,046.30 FS
94	1		*PANEL, SIDE GATE, LH	Bent	107.50 FS	*107.50 FS
95	1		*PILLAR SUB-ASSY, FR, LH	Serviceable	260.60 FS	*- FS
96	1		*REINFORCEMENT, FR BODY PILLAR, UPR LH	Bent	80.50 FS	*80.50 FS
97	1		*EXTENSION, ROCKER, OUTER LH	Bent	260.60 FS	*260.60 FS
98	1		*INSULATOR, BODY	Necessary	3.10 FS	*3.10 FS
99	1		*REINFORCEMENT SUB-AS	Serviceable	249.10 FS	*- FS
100	1		*STIFFENER, FIXTURE	Serviceable	14.30 FS	*- FS
101	1		*BRACKET, FIXTURE	Serviceable	12.80 FS	*- FS
102	1		*RAIL, ROOF SIDE, INN	Serviceable	143.70 FS	*- FS
103	1		*REINFORCEMENT, ROOF	Serviceable	57.50 FS	*- FS
104	1		*REINFORCEMENT, DOOR LOCK STRIKER, LH	Serviceable	198.40 FS	*- FS
105	1		*PANEL, VENTILATER CO	Serviceable	19.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
106	1		*REINFORCEMENT, DOOR	Serviceable	5.30 FS	*- FS
107	1		*PANEL, QUARTER, INNE	Serviceable	443.60 FS	*- FS
108	1		*REINFORCEMENT SUB-AS	Serviceable	378.40 FS	*- FS
109	1		*WEATHERSTRIP, FR DOO	Serviceable	217.60 FS	*- FS
110	4		*BOLT, WASHER BASED H	Not Necessary	25.20 FS	*- FS
111	1		*DOOR SUB-ASSY, FR AS	Serviceable	111.20 FS	*- FS
112	1		*PANEL SUB-ASSY, FR D	Serviceable	677.90 FS	*- FS
113	1		*PANEL SUB-ASSY, FR A	Serviceable	75.20 FS	*- FS
114	1		*PANEL, FR DOOR ARMRE	Serviceable	125.40 FS	*- FS
115	1		*ARMREST ASSY, DOOR	Serviceable	47.50 FS	*- FS
116	1		*GRIP ASSY, DOOR ASSI	Serviceable	118.90 FS	*- FS
117	1		*RETAINER	Serviceable	4.00 FS	*- FS
118	1		*LINK ASSY, DOOR CHECK	Bent	93.50 FS	*93.50 FS
119	1		*LOCK ASSY, DOOR, LH	Jammed	201.80 FS	*201.80 FS
120	1		*LINK, DOOR LOCK, LH	Serviceable	14.00 FS	*- FS
121	1		*STRIKER ASSY, DOOR	Serviceable	29.50 FS	*- FS
122	1		*COVER SUB-ASSY, FR D	Serviceable	7.80 FS	*- FS
123	1		*REGULATOR ASSY, FR D	Serviceable	790.00 FS	*- FS
124	1		*PLATE, DOOR SCUFF, L	Bent	52.50 FS	*52.50 FS
125	1		*COVER, STEP PLATE, L	Bent	332.00 FS	*332.00 FS
126	1		*SCREW, HEX LOBULAR	Necessary	3.60 FS	*3.60 FS
127	3		*SCREW, HEX LOBULAR	Necessary	5.40 FS	*5.40 FS
128	3		*NUT, SPRING	Necessary	9.90 FS	*9.90 FS
129	2		*NUT, SPRING	Necessary	8.00 FS	*8.00 FS
130	4		*RETAINER	Serviceable	13.20 FS	*- FS
131	1		*COVER, FR STEP, LH	Cracked	410.60 FS	*410.60 FS
132	4		*RETAINER	Necessary	13.20 FS	*13.20 FS
133	1		*CUSHION (3PCS)	Necessary (1Pc Only)	4.20 FS	*1.40 FS
134	3		*BOLT	Not Necessary	4.80 FS	*- FS
135	1		*BRACKET, TILT CAB ST	Bent	285.00 FS	*285.00 FS
136	1		*PLATE, STEP, LH	Cracked	257.80 FS	*257.80 FS
137	3		*BOLT	Not Necessary	6.30 FS	*- FS
138	1		*STAY, FR CORNER PANEL	Bent	19.00 FS	*19.00 FS
139	1		*PANEL SUB-ASSY, FR S	Distorted	355.40 FS	*355.40 FS
140	1		*SUPPORT SUB-ASSY, FR	Bent	323.20 FS	*323.20 FS
141	1		*COVER, STEP LWR, LH	Cracked	135.40 FS	*135.40 FS
142	3		*NUT, FLANGE	Necessary	3.00 FS	*3.00 FS
143	1		*MUDGUARD, FR FENDER	Cracked	81.20 FS	*81.20 FS
144	1		*MUDGUARD, SIDE, LH	Deformed	240.10 FS	*240.10 FS
145	1		*RETAINER (14PCS)	Necessary (1Pc Only)	23.80 FS	*1.70 FS
146	1		*RETAINER (6PCS)	Necessary (1Pc Only)	28.80 FS	*4.80 FS
147	1		*SPLASHBOARD SUB ASSY	Serviceable	532.30 FS	*- FS
148	4		*BOLT	Necessary	7.60 FS	*7.60 FS
149	1		*BRACKET SUB ASSY, FR	Bent	142.90 FS	*142.90 FS
150	1		*BRACKET SUB ASSY, FR	Bent	61.20 FS	*61.20 FS
151	1		*PANEL, FR FENDER SID	Bent	394.90 FS	*394.90 FS
152	5		*BOLT, SQUARE	Not Necessary	38.00 FS	*- FS
153	7		*NUT, FLANGE	Not Necessary	7.00 FS	*- FS
154	3		*NUT, SPRING	Not Necessary	12.00 FS	*- FS
155	2		*BOLT	Necessary	14.60 FS	*14.60 FS
156	1		*BRACKET SUB ASSY, FR	Necessary	57.70 FS	*57.70 FS
157	1		*LINER, FR, FENDER, LH	Cut	163.40 FS	*163.40 FS
158	1		*BRACKET SUB ASSY, SEA	Necessary	36.50 FS	*36.50 FS
159	3		*NUT, FLANGE	Not Necessary	3.00 FS	*- FS
160	1		*BOLT	Not Necessary	7.30 FS	*- FS
161	1		*PANEL SUB-ASSY, INSTR	Serviceable	1,240.80 FS	*- FS
162	1		*DUCT, HEATER TO REGI	Serviceable	253.30 FS	*- FS
163	1		*DUCT, HEATER TO REGI	Serviceable	101.70 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
164	1		*DUCT, HEATER TO FOOT	Serviceable	64.50 FS	*- FS
165	1		*REINFORCEMENT ASSY	Serviceable	849.00 FS	*- FS
166	1		*NOZZLE ASSY, DEFROST	Serviceable	267.30 FS	*- FS
167	1		*HPSE, DEF	Serviceable	45.30 FS	*- FS
168	1		*HOSE, DEF	Serviceable	45.30 FS	*- FS
169	2		*RETAINER	Serviceable	4.20 FS	*- FS
170	1		*MEMBER, HOOD	Serviceable	50.50 FS	*- FS
171	1		*WEATHERSTRIP, FR CORN	Serviceable	82.70 FS	*- FS
172	1		*SEAL, FR PANEL LWR RH	Serviceable	103.40 FS	*- FS
173	1		*SEAL, FR PANEL, LWR LH	Serviceable	103.50 FS	*- FS
174	1		*STAY SUB-ASSY, OUT R	Bent	603.40 FS	*603.40 FS
175	1		*STAY, OUTER RR VIEW	Bent	89.70 FS	*89.70 FS
176	1		*MOULDING	Necessary	457.10 FS	*457.10 FS
177	2		*SIKA 182010 SIKA TACK GO! (BLA	Necessary	216.00 FS	*216.00 FS
178	2		*SIKA 207. G+P ADHESIVE PRIMER	Necessary	400.00 FS	*400.00 FS
179	1		*GARNISH ASSY, FR PILLAR LH	Serviceable	98.20 FS	*- FS
180	1		*BOARD, QUARTER TRIM	Serviceable	236.80 FS	*- FS
181	1		*COVER, SHOULDER BELT	Serviceable	38.30 FS	*- FS
182	1		*WEATHERSTRIP, FR DOO	Necessary	292.30 FS	*292.30 FS
183	1		*GRIP SUB-ASSY, ASSIS	Serviceable	156.40 FS	*- FS
184	1		*GRIP SUB-ASSY, INSTR	Serviceable	139.20 FS	*- FS
185	2		*COVER, ASSIST GRIP	Serviceable	16.60 FS	*- FS
186	2		*BOLT	Not Necessary	3.80 FS	*- FS
187	2		*BOLT	Not Necessary	10.60 FS	*- FS
188	1		*UNITASSY, AIR CONDIT	Serviceable	2,126.20 FS	*- FS
189	1		*BLOWER ASSY	Serviceable	838.50 FS	*- FS
190	1		*HOSE SUB-ASSY, DISCH	Bent	426.10 FS	*426.10 FS
191	1		*TUBE SUB ASSY, LIQUID	Bent	298.30 FS	*298.30 FS
192	1		*HOSE SUB-ASSY, SUCTI	Bent	390.70 FS	*390.70 FS
193	1		*TUBE, LIQUID	Serviceable	86.20 FS	*- FS
194	1		*HOSE SUB-ASSY, SUCTI	Serviceable	390.70 FS	*- FS
195	1		*TUBE, LIQUID	Bent	86.20 FS	*86.20 FS
196	1		*BRACKET, CONDENSER	Bent	57.70 FS	*57.70 FS
197	1		*CONDENSER ASSY	Broken	1,898.90 FS	*1,898.90 FS
198	1		*BRACKET SUB ASSY, COO	Bent	107.20 FS	*107.20 FS
199	1		*WIRE, HEATER CONTROL	Cut	51.50 FS	*51.50 FS
200	1		*HEADLAMP ASSY	Serviceable	750.30 FS	*- FS
201	1		*HEADLAMP ASSY, LH	Cracked	750.30 FS	*750.30 FS
202	1		*LAMP ASSY, CORNERING	Serviceable	148.70 FS	*- FS
203	1		*LAMP ASSY, CORNERING	Cracked	148.70 FS	*148.70 FS
204	1		*RETAINER (4PCS)	Necessary (1Pc Only)	9.60 FS	*2.40 FS
205	1		*SCREW, BIDDING TAPPI (4PCS)	Necessary (1Pc Only)	9.20 FS	*2.30 FS
206	1		*LAMP ASSY, FR TURN S	Serviceable	156.40 FS	*- FS
207	1		*LAMP ASSY, FR TUBE S	Missing	156.40 FS	*156.40 FS
208	1		*LAMP ASSY, SIDE TURN	Serviceable	93.20 FS	*- FS
209	1		*COVER SUB-ASSY, SIDE	Serviceable	1,101.90 FS	*- FS
210	1		*COVER SUB-ASSY, STEP	Serviceable	1,061.70 FS	*- FS
211	1		*SPRING ASSY, TILT CA	Serviceable	2,875.20 FS	*- FS
212	1		*BRACKET SUB-ASSY, TI	Serviceable	525.50 FS	*- FS
213	1		*BRACKET SUB-ASSY, TI	Serviceable	525.50 FS	*- FS
214	1		*LEVER SUB-ASSY, TILT	Serviceable	3,423.40 FS	*- FS
215	2		*ABSORBER ASSY, CAB F	Serviceable	362.00 FS	*- FS
216	2		*SPRING ASSY, CAB FR	Serviceable	789.80 FS	*- FS
217	2		*ABSORBER ASSY, CAB R	Serviceable	525.60 FS	*- FS
218	2		*ABSORBER ASSY, CAB R	Serviceable	525.60 FS	*- FS
219	2		*SPRING ASSY, CAB RR	Serviceable	897.20 FS	*- FS
220	1		*CLAMP, BRAKE PIPE	Necessary	5.50 FS	*5.50 FS
221	1		*BRACKET SUB-ASSY, TILT CAB PUMP	Bent	230.60 FS	*230.60 FS
222	1		*PUMP ASSY, TILT CAB	Not Working	2,909.10 FS	*2,909.10 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
223	1		*BRACKET SUB-ASSY, ST	Serviceable	944.40 FS	*- FS
224	1		*CROSSMEMBER SUB-ASSY	Serviceable	739.30 FS	*- FS
225	1		*STAY SUB-ASSY, FR UN	Serviceable	1,747.60 FS	*- FS
226	1		*BRACKET, HOOK SUPPOR	Serviceable	309.20 FS	*- FS
227	1		*BRACKET SUB-ASSY, HE	Serviceable	202.60 FS	*- FS
228	1		*BRACKET SUB-ASSY, HE	Serviceable	202.60 FS	*- FS
229	1		*STAY, HEADLAMP, NO.2	Serviceable	49.30 FS	*- FS
230	1		*STAY, HEADLAMP, NO.2	Serviceable	49.30 FS	*- FS
231	1		*HOOK ASSY, PINTLE	Serviceable	667.10 FS	*- FS
232	1		*STAY SUB-ASSY, AIR CL	Serviceable	172.90 FS	*- FS
233	1		*CLEANER ASSY, AIR	Serviceable	1,436.60 FS	*- FS
234	1		*PLATE, FENDER APRON	Serviceable	21.00 FS	*- FS
235	1		*MEMBER SUB-ASSY, FR	Serviceable	550.50 FS	*- FS
236	1		*SPLASHBOARD, SIDE, L	Serviceable	178.10 FS	*- FS
237	1		*MUDGUARD	Serviceable	48.50 FS	*- FS
238	1		*SEAL, ENG ROOM	Not Necessary	67.00 FS	*- FS
239	1		*HOLDER SUB-ASSY, FR MUDGUARD	Serviceable	91.70 FS	*- FS
240	2		*BOLT, CAB MOUNTING	Necessary	131.40 FS	*131.40 FS
241	1		*PLATE, STEP	Repeated	257.80 FS	*- FS
242	1		*JAR & PUMP ASSY, WASH	Deformed	276.50 FS	*276.50 FS
243	1		*HOLDER	Necessary	5.00 FS	*5.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	78,069.40	36,379.80
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE AND REFOCUS HEADLAMP	New	149.60	149.60
2	REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR	New	880.00	880.00
3	R/I DASHBOARD ASSY TO FAC REPAIR	New	1,760.00	1,760.00
4	R/1 FRONT WINDSCREEN GLASS	New	880.00	880.00
5	CHECK WIRING AND CONDUCT WATER TEST	New	149.60	149.60
6	R/I AC CON BLOWER ASSY TO FAC REPAIR & REGAS	New	880.00	880.00
7	R/I WIREHARNES ASSY TO FAC REPAIR	New	880.00	880.00
8	R/I BRAKE BOOSTER SYSTEM TO FAC REPAIR	New	880.00	0.00
9	REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR	New	880.00	880.00
10	R/I ROOF LINING TO FAC REPAIR	New	1,760.00	0.00
11	RESET ECU AND REPROGRAMME	New	220.00	220.00
12	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN / REALIGN AC AFFECTED AREAS	New	8,800.00	4,400.00
13	RESPRAY ACC AFFECTED AREAS	New	6,600.00	3,960.00
14	TO REPLACE FLOOR PANEL, RH REAR QUARTER PANEL	New	3,520.00	3,520.00
15	TO RESPRAY FLOOR PANEL AND RH REAR QUARTER PANEL	New	1,320.00	1,320.00
16	SUPPLY LH FRONT TYRE	New	1,800.00	1,800.00
Gross Labour Cost (\$)			31,359.20	21,679.20

Report was unsubmitted during this print-out.

< END OF ESTIMATES >